

Source:
Knight, Bill, 2006

N
W E
S

Progress Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

Location of Energy Losses Experienced by a Tsunami Generated at Source Location 1: The Puerto Rico Trench

FIGURE 2.4.6-216 Rev 0