

See Table 2.6-6 for description of soil horizons. (Photographs FHS00/8-2#3 through FHS00/8-2#12 taken on August 1, 2000).

FSAR UPDATE
HUMBOLDT BAY ISFSI
FIGURE 2.6-45 RELICT SOIL AND UPPER HOOKTON FORMATION DEPOSITS EXPOSED IN TRENCH GMX-72 (NW WALL AT STATION 180 FT)

Revision 0 January 2006



FSAR UPDATE
HUMBOLDT BAY ISFSI
FIGURE 2.6-46
Structure contour map of the Little Salmon fault north of Humboldt Hill (after Woodward-Clyde Consultants, 1980, Figure C-14). Cross section A-A' shown on Figure 2.6-49.