

FIGURE 6.4-202
Hydrogen Fluoride Concentrations at the Control Room HVAC Intake and Inside the Control Room for Stability Class E and the Wind Speed of 4 m/sec case