

N
W E
S

LEGEND

- Proposed AP1000 Structures
- HNP Unit 1
- 1-km (0.6-mi.) Radius from Site
- Railroad
- Highway
- Roads
- LIDAR Lineaments (this study)
  FPL - Fire Pond Lineament
- Faults (dashed where inferred, dotted where concealed) (Ebasco, 1975, CP&L, 1983, NCGS, 1985, Wooten et al., 1996, Harding Lawson, 1997, and NCGS, 2006)
  HF - Harris Fault
  SBPF - South Borrow Pit Fault
  W8 - W8 Fault
  W82 - W82 Fault
- Point Fault (NCGS, 2006)
- Dikes (dashed where inferred) (CP&L, 1983, NCGS, 1985, NCGS, 2006, and Technos this study)
- Strike and Dip of Bedding

Geologic Units (See Figure 2.5.1-231, Sheet 2 for Unit Descriptions)

- 25 — Thickness of Fill (feet)
- Qal
- Trcs/si2
- Trcsi/s
- Trcs

Base Map: Shaded Relief Map from LIDAR (NC DOT, 2005)

Grid is in the NAD 83 North Carolina State Plane Coordinate System (feet)

0 125 250 500 750 1,000
Meters

0 500 1,000 2,000 3,000
Feet

Progress Energy Carolinas

Shearon Harris Nuclear Power Plant
Units 2 and 3
Part 2, Final Safety Analysis Report

New Hill, North Carolina

Geologic Map of the Site Location
(1-km [0.6-mi.] Radius)

FIGURE 2.5.3-206

Rev. 1