

PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

Rock Deaggregation for 1 and 2.5 Hz at Amplitudes Corresponding to 10^{-4} Annual Frequency of Exceedence

FIGURE 2.5.2-25

Rev 0