

PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

Rock Deaggregation for 5 and 10 Hz at Amplitudes Corresponding to 10^{-6} Annual Frequency of Exceedence

FIGURE 2.5.2-30

Rev 0