Assessment of Ultrasonic Phased Array Inspection Method for Welds in Cast Austenitic Stainless Steel Pressurizer Surge Line Piping

U.S.NRC
UNITED STATES NUCLEAR REGULATORY COMMISSION
Protecting People and the Environment

Carol Nove
Materials Engineer
Division of Component Integrity, NRR
June 10, 2010

U.S.NRC
UNITED STATES NUCLEAR REGULATORY COMMISSION
Protecting People and the Environment

Outline

- Issue Summary
- Background
- CASS Materials
- PA-UT Examinations
- PA-UT Examination Results
- Conclusion

U.S.NRC
UNITED STATES NUCLEAR REGULATORY COMMISSION
Protecting People and the Environment

Issue Summary

- CASS usage is prevalent in Class 1 reactor components, especially in Westinghouse reactors
- CASS has many advantageous properties
- CASS is susceptible to thermal aging
- Course-grained microstructure makes CASS difficult to inspect
- Concern is that low toughness material containing casting defects or service-induced flaws could fail during loading transients

Background

- Previous work focused on heavy-walled primary loop piping with outer diameter measurements ranging from 71.12 to 91.44 cm (28 to 36 in.)

- CASS material in the Primary Coolant System in a Westinghouse Designed PWR 3-loop Plant shown at right *(courtesy of Chockie Group International)*



Background (cont.)

- Thinner cast piping found pressurizer surge lines and safe ends with OD msmts ranging from 20.48 to 35.56 cm (12 to 14 in.) and wall thicknesses from 3.05 to 4.32 cm (1.2 to 1.7 in.)

- CASS material in the Primary Coolant System in a Combustion Engineering Designed PWR 2-loop Plant shown at right



Background (cont.)

- Set of thermal fatigue cracks implanted into three CASS pressurizer surge-line pipe-to-elbow welds
  - Vintage CASS materials formed in the 1970's used
  - Material salvaged from Combustion Engineering designed units that were never brought into full operation
- Specimens sliced, polished, and chemically etched for microstructural analysis
- Baseline CASS material noise analysis conducted
- Phased array ultrasonic examinations performed

CASS Materials

Photographs of the Side-View (left) and End-View (right) of the CASS PZR Ring Segment (specimen 7C-059)





Photographs of Polished and Chemically Etched CASS PZR Ring Segment (specimen 7C-059) Showing the Pipe-Side (CCSS) Grain Microstructure (left) and the Elbow-Side (SCSS) Grain Microstructure (right)

CASS Materials



WNP-3 Surge Line Section Showing the Locations of the Pipe and Elbow Cuts to Produce Two Pipe-to-Elbow Specimens, 9C-001 and 9C-002. The centrifugally cast pipe microstructures are displayed for both specimens.

CASS Materials

- Grain diameter measurements from three PZR surge-line specimens

	Surge Line 1 Grain Diameter (7C-059), mm (in.)		WNP3 Surge Line Grain Diameter (9C-001 and 9C-002), mm (in.)		
	Elbow	Pipe	Elbow	Pipe Center	Pipe Outside
Average	2.6 (0.10)	1.9 (0.07)	10.3 (0.41)	6.6 (0.26)	3.5 (0.14)
Minimum	0.5 (0.02)	0.6 (0.02)	2.6 (0.10)	1.3 (0.05)	0.8 (0.03)
Maximum	6.3 (0.25)	6.7 (0.26)	41.0 (1.61)	25.6 (1.01)	13.9 (0.55)

CASS Materials

End View Illustrations of Implanted Flaws



Specimen 7C-059



Specimen 9C-001



Specimen 9C-002

CASS Materials

True-state dimensions and locations of all implanted thermal fatigue flaws for three specimens. All flaws are oriented in circumferential direction.

Flaw	Flaw Location	Flaw Length, cm (in.)	Flaw Depth (Height) in % of thickness	Degree Location
1-1	Weld Centerline	10.2 (4.0)	35.2% T	45°
1-2	Pipe Side Near Fusion Line	5.1 (2.0)	30.3% T	120°
1-3	Weld Centerline	5.1 (2.0)	29.8% T	210°
1-4	Weld Centerline	15.2 (6.0)	30.4/50.2% T	300°
2-1	Weld Centerline	7.6 (3.0)	10/20% T	0°
2-2	Weld Centerline	5.1 (2.0)	28.6% T	90°
2-3	Weld Centerline	6.4–7.6 (2.5–3.0)	27.1% T	270°
3-1	Weld Centerline	7.6 (3.0)	16/25.1% T	0°
3-2	Weld Centerline	5.1 (2.0)	20.6% T	90°
3-3	Weld Centerline	6.4–7.6 (2.5-3.0)	16% T	270°

Set-up on Pressurizer Surge Line Specimen 7C-059

- Configured for standard PA-UT.
- Pipe-end on right side.
- Elbow-end on left side.





Guide ring, translation slide, and floor to ceiling brace shown to left.

PA UT Examinations

- Phased Array Ultrasonic (PA-UT) Examinations
  - To evaluate detection, localization, and sizing performance as function of frequency.
  - Four custom-designed PA-UT probes used:
    - 800 kHz, 1.0 MHz, 1.5 MHz, and 2 MHz
    - Inspection angles – 30° to 70° in 1° increments
    - Data collected from both the CCSS pipe side and the SCSS elbow sides of the weld

PA-UT Examination Results

Specimen 9C-002, Flaw 1





PA-UT Examination Results

- **Flaw 1 of 9C-002**
- **800 kHz**
- **merged image for length sizing**



from pipe side



from elbow side

PA-UT Examination Results

- **Flaw 1 of 9C-002**
- **1.0 MHz**
- **merged image for length sizing**



from pipe side



from elbow side

PA-UT Examination Results

- **Flaw 1 of 9C-002**
- **1.5 MHz**
- **merged image for length sizing**

from pipe side



from elbow side



PA-UT Examination Results

- **Flaw 1 of 9C-002**
- **2.0 MHz**
- **merged image for length sizing**



from pipe side



from elbow side

PA-UT Examination Results

Length Sizing Summary of Results

		800 kHz		1.0 MHz		1.5 MHz			2.0 MHz	
Specimen/ Flaw	**True-State Length, mm**	**CCSS, mm**	**SCSS, mm**	**CCSS, mm**	**SCSS, mm**	**CCSS, mm**	**Raster CCSS, mm**	**SCSS, mm**	**CCSS, mm**	**SCSS, mm**
7C-059										
1	101.6	104.7	114.9	116.1	112.9	116.5		102.4	119.3	96.6
2	50.6	63.0	19.1	69.2	61.4	34.8		34.8	36.0	57.1
3	50.6	72.0	--	49.3	39.3	49.7		74.0	45.8	62.4
4	152.6	190.5	160.2	186.4	181.2	187.3		181.3	181.4	143.3
9C-001										
1	76.6	89.3	92.3	96.3	94.5	91.5	76.6	83.3	104.4	77.4
2	51.1	56.4	74.5	59.2	72.8	64.1	51.1	46.8	37.8	57.8
3	69.7	77.1	69.4	70.3	77.1	88.4	69.7	69.1	93.2	64.0
9C-002										
1	76.7	68.6	79.9	100.3	96.5	62.0	88.2	79.0	101.3	90.5
2	50.5	53.2	67.2	57.4	73.9	53.3	50.3	63.3	54.1	66.9
3	69.7	60.8	70.2	68.0	91.0	55.3	54	55.3	53.8	71.9
RMSE		***15.7***	***16.0***	***16.6***	***18.5***	***16.9***	***8.0***	***14.4***	***19.4***	***9.1***

PA-UT Examination Results

Depth Sizing Summary of Results

		800 kHz		1.0 MHz		1.5 MHz			2.0 MHz	
Specimen/ Flaw	**True-State Length, mm**	**CCSS, mm**	**SCSS, mm**	**CCSS, mm**	**SCSS, mm**	**CCSS, mm**	**Raster CCSS, mm**	**SCSS, mm**	**CCSS, mm**	**SCSS, mm**
7C-059										
1	10.9	12.6	11.5	10.6	11.8	10.9		11.5	11.4	10.6
2	9.3	11.6	9.6	11.3	9.1	9.2		8.3	10.9	10.5
3	9.3	9.8	--	10.4	10.0	10.6		10.0	11.1	10.3
4	15.6	16.3	14.5	15.0	14.7	14.5		14.9	15.0	15.3
9C-001										
1a	3.4	5.0	4.0	3.4	3.2	4.2	3.5	2.5	3.5	5.2
1b	6.4	7.5	7.9	5.8	6.2	5.7	5.2	7.7	6.1	6.9
2	8.9	8.6	8.0	7.7	7.1	8.1	7.1	9.2	11.5	11.2
3	8.3	11.1	7.2	9.7	9.0	8.8	7.8	7.7	10.3	9.0
9C-002										
1a	4.8	4.3	6.9	4.8	NA	4.3	4.2	4.5	4.4	5.8
1b	7.5	9.5	7.9	9.3	6.4	7.4	6.5	4.6	7.9	9.0
2	6.3	6.4	8.1	7.9	8.2	6.6	6.7	4.4	6.0	7.0
3	4.8	6.3	NA	6.5	3.6	5.3	8.3	5.1	6.0	6.9
RMSE		***1.5***	***1.8***	***1.2***	***1.7***	***0.7***	***1.5***	***1.2***	***1.3***	***1.3***

PA-UT Examination Results

Signal-to-Noise Ratio Summary of Results

	800 kHz		1.0 MHz		1.5 MHz			2.0 MHz	
Specimen/ Flaw	CCSS, dB	SCSS, dB	CCSS, dB	SCSS, dB	CCSS, dB	Raster CCSS, dB	SCSS, dB	CCSS, dB	SCSS, dB
7C-059									
1	17.0	15.7	16.6	18.3	14.7		18.7	18.2	22.4
2	13.7	10.4	14.2	11.4	14.3		11.6	16.9	11.1
3	14.5	--	16.2	9.5	17.7		17.5	19.9	18.1
4	15.1	17.4	16.3	15.8	17.3		16.6	15.7	19.0
9C-001									
1	20.0	15.2	20.7	14.2	21.1	22.6	16.3	19.4	18.1
2	19.6	15.5	18.9	14.0	17.8	21.3	15.1	20.7	15.6
3	17.4	13.7	17.2	18.1	16.4	17.4	18.9	15.5	16.7
9C-002									
1	16.6	24.6	16.8	22.6	17.6	18.4	11.2	18.3	16.5
2	13.9	20.0	14.9	21.0	15.9	19.7	21.7	17.5	19.9
3	17.2	16.7	18.0	19.7	18.1	18.9	17.3	17.1	17.9

PA-UT Examination Results

Map of true-state and measured circumferential flaw localization data for specimen 7C-059



PA-UT Examination Results

Map of true-state and measured circumferential flaw localization data for specimen 9C-001



PA-UT Examination Results

Map of true-state and measured circumferential flaw localization data for specimen 9C-002



U.S.NRC
UNITED STATES NUCLEAR REGULATORY COMMISSION
Protecting People and the Environment

Conclusion

- State-of-the-art phased array inspection approaches are rapidly evolving and have enabled this demonstration of the capability to reliably detect and effectively characterize 10% - 50% through wall thermal fatigue cracks in cast austenitic stainless steel components where the wall thickness is less than 50 mm (2 in.).
- PA-UT data obtained using inspection frequencies ranging from 800 kHz to 2.0 MHz yielded strong signal-to-noise ratios and provided accurate length and depth sizing results.