RM 28
1K-3K
3K-4K
Bkgd - 1K
4K-7K
Bkgd - 1K
RM 28A
Bkgd - 1K
UP
Bkgd
Bkgd
RM 27
504K
32K
4K-7K
323K
192K
18K-21K
5K-7K
133K
4K-7K
100K
400K
5K-7K
11K-13K
3K-5K
Bkgd - 2K
RM 26
Bkgd - 1K
Bkgd - 1K
Bkgd - 1K
RM 25
Bkgd - 1K
2K - 3K (Mezz)
Bkgd - 1K
3K-5K On Wall in Mezz
Bkgd - 2K
Bkgd - 1K
Bkgd - 2K
2K-3K
Bkgd - 2K
Bkgd - 2K
Bkgd - 2K
UP
Bkgd - 2K
Bkgd - 2K
RM 23
Bkgd - 1K
RAMP UP
MEN
WOMEN
Bkgd - 1K
3K-5K On Wall
Bkgd - 2K
RM 2
Bkgd
Bkgd
RM 3
Bkgd
RM 1A
Bkgd
Bkgd
Bkgd
Bkgd
RM 4
RM 5
RM 6
RM 1
Bkgd - 1K
Bkgd - 1K
RM 1B
Bkgd
2K-3K Ceiling
7K-9K Ceiling Beam
3K-5K On Wall
EXT.
8K-11K
1K-2K
136K
RM 17A
Bkgd - 1K
127K
25K
2K-3K
7K-9K
RM 17
Bkgd
Bkgd
DN
Bkgd - 1K
RM 18
RM 18A
Bkgd
RM 16
Bkgd
EXT.
163K
443K
173K
7K-9K
53K- 93K
33K- 53K
173K
573K
DN
31K
5K-9K
90K
77K
149K
77K
3K-4K
Bkgd - 1K
RM 12
33K-43K
18K-53K
733K
443K
33K-73K
33K-43K
9K-11K
31K
23K-53K
18K-23K
31K
31K
31K
135K
RM 12A
33K-73K
17K-21K
7K-9K
RM 13
103K
133K
13K-33K
RM 13A
7K-9K
17K-53K
3K-5K
SUMP
435K
13k-33K
RM 15
RM 11
RM 9
3K-4K
2K-3K
Bkgd - 1K
Bkgd
RM 10
Bkgd
RM 7
Bkgd - 1K
ELEV E000
EXT.

Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri
Pickard Hall
Characterization Report
Gamma Scans

CHASE Environmental Group

Building: Pickard Hall | Elevation: Basement | Page: F.1 of F.4



Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri
Pickard Hall
Characterization Report
Gamma Scans

CHASE Environmental Group

Building: Pickard Hall	Elevation: 1st Floor	Page: F.2 of F.4



Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri
Pickard Hall
Characterization Report
Gamma Scans

CHASE Environmental Group

Building: Pickard Hall	Elevation: 2nd Floor	Page: F.3 of F.4



Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri
Pickard Hall
Characterization Report
Gamma Scans

CHASE Environmental Group

Building: Pickard Hall	Elevation: Attic	Page: F.4 of F.4