

University of Missouri
Pickard Hall
Characterization Report
Gamma Scans

CHASE Environmental Group

Building: Pickard Hall	Elevation: Basement	Page: F.1 of F.4



Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri Pickard Hall Characterization Report Gamma Scans		CHASE Environmental Group
Building: Pickard Hall	Elevation: 1st Floor	Page: F.2 of F.4



Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri Pickard Hall Characterization Report Gamma Scans		CHASE Environmental Group
Building: Pickard Hall	Elevation: 2nd Floor	Page: F.3 of F.4



Gamma scan results are in net cpm, corrected for a background of 7K cpm

University of Missouri
Pickard Hall
Characterization Report
Gamma Scans

CHASE Environmental Group

Building: Pickard Hall	Elevation: Attic	Page: F.4 of F.4