

FIGURE 2.4.4-207
Norris Dam - Postulated Condition of Dam after Failure SSE and 25-Year Flood