

Figure 2.5.4-232 Peak Strength of Limestone from Consolidated-Undrained and Unconsolidated-Undrained Triaxial Tests