

Source:
Atlantic and Gulf of Mexico Tsunami Hazard Assessment Group, 2007

N
W E
S

Progress Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

Summary Map Showing the Size, Distribution, and Composition of Landslides in the Three Provinces
FIGURE 2.4.6-206 Rev 0