

Projection: NAD 1983 UTM Zone 18 N

LEGEND

- Extent of investigation for Summit Site, DE
- Wells and borings investigated by Benson, 2006 (Reference 2.5.1-18)
- Wells and borings investigated by Sugarman and Monteverde, 2008 (Reference 2.5.1-215)
- Geologic cross-section lines (Reference 2.5.1-18)
- Geologic cross-section lines (Reference 2.5.1-215)

Proposed Faults and Lineaments mapped by Spoljaric

Mapped from Satellite Imagery

- Spoljaric, 1979 (Reference 2.5.1-213)
- Spoljaric, 1974 (Reference 2.5.1-212)

Basement Faults

- Spoljaric, 1972 (Reference 2.5.1-210)
- Spoljaric, 1973 (Reference 2.5.1-211)

PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

New Castle County Faults

FIGURE 2.5.1-19

Rev 0