

Duke Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

PMF Inflow Hydrograph to
Lake Rousseau

FIGURE 2.4.3-221 Rev 6