

U.S. Nuclear Regulatory Commission  
Office of Public Affairs, Region IV  
611 Ryan Plaza Drive - Suite 400  
Arlington, Texas 76011-8064

RIV: 98-10  
CONTACT: Breck Henderson  
OFFICE: 817/860-8128

FOR IMMEDIATE RELEASE  
March 13, 1998

### NRC SPECIAL INSPECTION TEAM SENT TO WNP-2

The Nuclear Regulatory Commission has sent a three-man inspection team to WNP-2, a nuclear reactor operated by the Washington Public Power Supply System (WPPSS) near Richland, Washington, to look into circumstances surrounding an automatic reactor shutdown that occurred Wednesday, March 11.

The shutdown was caused by a broken air line that allowed one of the plant's main steam system isolation valves to go shut. All safety equipment functioned normally, and there were no injuries or releases of radioactive material. However, the NRC staff has questions regarding the response of WNP-2 operators and some equipment indications that did not initially appear to be as expected for such an event.

The inspectors arrived at the plant March 12 and are continuing with their activities.

###