**DIRS** 

Change Notice 09-019				
	DELETED:		TRANSMITTED:	
	<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1.			IP 65001.D	08/05/09
2.			IP 65001.09	08/05/09
3.		<del></del>	IP 65001.13	08/05/09
4.	IP 81073	05/09/84	IP 81073	08/05/09

TRAINING: None

REMARKS: The following inspection procedures are issued to provide initial guidance for Inspections, Tests, Analyses, and Acceptance Criteria (ITAAC) related inspections under 10 CFR Part 52:

> IP 65001.D (Inspection of the ITAAC-Related Operational Testing Program)

IP 65001.09 (Inspection of ITAAC-Related Installation of Electric and Fiber Optic Cable)

IP 65001.13 (Inspection of ITAAC-Related Installation of Load Handling Equipment and Fuel Racks)

IP 81073 (Access Control (Fuel Facility) - Packages, Material, and Strategic Special Nuclear Material (SSNM)) has been revised to: (1) emphasize the risk-informed, performance-based approach to inspection and (2) impose changes to inspection activities due to orders issued that have not been incorporated by rulemaking.

DISTRIBUTION: Standard for IP 65001.D, IP 65001.09, and IP 65001.13.

Distribution for IP 81073, has been designated as containing "Official Use Only - Security-Related Information" and is therefore not available to the public. For information on this IP, please contact Oleg Bukharin at 301-415-3551 or Larry Harris at 301-415-5072.

**END** 

Issue Date: 08/05/09 -2- 09-019