| Change Notice 15-004 | | | | |
|----------------------|---------------|-------------|--------------|-------------|
| | DELETED: | <u> </u> | TRANSMITTED: | |
| | <u>Number</u> | <u>Date</u> | Number | <u>Date</u> |
| 1. | IMC 2506 | 10/15/14 | IMC 2506 | 03/16/15 |
| 2. | IP 88002 | 10/30/08 | | |
| 3. | IP 88003 | 08/10/98 | IP 88003 | 03/16/15 |
| 4. | IP 88075 | 07/28/06 | IP 88075 | 03/16/15 |

TRAINING: No

REMARKS: IMC 2506, "Construction Reactor Oversight Process General Guidance and

Basis Document," has been revised to add guidance for inspection activities

during a lapse in appropriations.

IP 88002, "Operational Event Review and Feedback Programs at Fuel Facilities," has been deleted. The focus of the IP has been added to IP 88020.

IP 88003, "Reactive Inspection for Events at Fuel Cycle Facilities," has been revised to comply with format requirements in IMC 0040, as well as remove the requirement to perform an independent root cause analysis, and all references to allegation related material. The term "Special Inspection," has been replaced by "Reactive Inspection," to align with the procedure title. The definition section has been streamlined, and IMC 2683 has been added to the reference list.

IP 88075, "Event Follow-Up," has been revised to comply with format requirements in IMC 0040, remove all references to charge codes, and remove all references to specific documentation, and all event-related documentation is tracked in another system.

DISTRIBUTION: Standard

END