

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 24

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 24

Facility Name: Oconee 3 Docket (050- 00287)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00287/2009-006
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00287/2009-00M
111 - Procedure / reference document technical content	C - Chemistry	C - Calibration	050-00287/2009-00M
Number of Items for this Docket: 3			
Percent of Total for this Docket: 13			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	G - Engineering	G - Design	050-00287/2009-006
144 - Audit / self-assessment / effectiveness review LTA	M - Mechanical	M - Maintenance / Repair	050-00287/2009-00M
144 - Audit / self-assessment / effectiveness review LTA	I - Instrumentation & Control	C - Calibration	050-00287/2009-00M
Number of Items for this Docket: 3			
Percent of Total for this Docket: 13			
Work Planning & Practices / IR			
182 - Work package quality LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00287/2009-00M
183 - Pre-job activities LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00287/2009-00M
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00287/2009-003
185 - Procedural adherence LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00287/2009-00M
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00287/2009-003
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00287/2009-00M
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00287/2009-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00287/2009-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00287/2009-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00287/2009-006
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00287/2009-003
197 - Self-check LTA	I - Instrumentation & Control	C - Calibration	050-00287/2009-00M
197 - Self-check LTA	M - Mechanical	M - Maintenance / Repair	050-00287/2009-00M
Number of Items for this Docket: 13			
Percent of Total for this Docket: 54			
Human-System Interface & Environmnt / LER			
170 - HSI or information availability / quality LTA	E - Electrical	M - Maintenance / Repair	050-00287/2009-002-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 24
National Average: 46
2x National Average: 92
National Median: 23
Average for Selected Dockets: 24**

Facility Name: Oconee 3 Docket (050- 00287)

Details

Procedures & Reference Document / LER

110 - No procedure / reference documents

111 - Procedure / reference document technical content

Department

E - Electrical

E - Electrical

Work Type

M - Maintenance / Repair

M - Maintenance / Repair

Docket/Report

050-00287/2009-002-00

050-00287/2009-002-00

Number of Items for this Docket: 2

Percent of Total for this Docket: 8

Work Planning & Practices / LER

190 - Failure to stop work / non-conservative decision making

193 - Non-conservative action

E - Electrical

E - Electrical

M - Maintenance / Repair

M - Maintenance / Repair

050-00287/2009-002-00

050-00287/2009-002-00

Number of Items for this Docket: 2

Percent of Total for this Docket: 8

Total Items for this Docket: 24
