

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 18

Facility Name: McGuire 2 Docket (050- 00370)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
171 - Simulator fidelity LTA	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Oversight / IR			
130 - Inadequate suprevison / command and control	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
131 - Management expectations or directions LTA	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Problem Identification & Resolution / IR			
150 - Programmatic deficiency	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
189 - Recognition of adverse condition / questioning attitude LTA	D - Emergency Planning	D - Emergency Drill	050-00370/2009-501
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
Human-System Interface & Environmnt / LER			
170 - HSI or information availability / quality LTA	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
111 - Procedure / reference document technical content	I - Instrumentation & Control	T - Testing	050-00370/2010-002-01
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
Problem Identification & Resolution / LER			
140 - Problem not completely or accurately identified	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 18

Facility Name: McGuire 2 Docket (050- 00370)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / LER			
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
143 - Tracking / trending LTA	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
150 - Programmatic deficiency	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
Number of Items for this Docket: 4			
Percent of Total for this Docket: 22			
<hr/>			
Work Planning & Practices / LER			
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
186 - Failure to take action / meet requirements	I - Instrumentation & Control	T - Testing	050-00370/2010-002-01
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00370/2010-001-00
187 - Action implementation LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00370/2010-002-01
Number of Items for this Docket: 4			
Percent of Total for this Docket: 22			
<hr/>			
Total Items for this Docket: 18			
