

Mr. Aron Seiken, President
Nuclear Logisitcs, Inc. (NLI)
7410 Pebble Drive
Fort Worth, TX 76118

SUBJECT: VENDOR INSPECTION OF NUCLEAR LOGISTICS, INC.

Dear Mr. Seiken:

This letter documents the Nuclear Regulatory Commission (NRC) staff's plan to perform an inspection of Nuclear Logistics, Inc. to review implementation of your quality assurance program in accordance with Title 10 of the *Code of Federal Regulations* Part 50, Appendix B. Specifically, the quality assurance program will be reviewed as it pertains to Nuclear Logistics' procurement documentation and design control and testing of the 480v breaker modification for Fort Calhoun Station in 2009 that resulted in breaker fires at the Fort Calhoun Station.

As discussed during a conference call on August 1, 2012, the inspectors plan to arrive at facility, on Monday, August 27, 2012, and will conduct the inspection through Friday, August 31, 2012. Subsequent to the inspection, a report will be issued and transmitted to you via letter. The lead inspector for this effort is Mr. Douglas Bollock; you may contact him at 301-415-6609 or via electronic mail at Douglas.Bollock@nrc.gov.

The following docket number has been assigned to your facility: 999-01298. Please reference this number on any correspondence sent to the NRC.

Sincerely,

/RA/

Richard A. Rasmussen, Chief
Electrical Vendor Branch
Division of Construction Inspection
and Operational Programs
Office of New Reactors

Docket No.: 999-01298

Mr. Aron Seiken, President
Nuclear Logisitcs, Inc. (NLI)
7410 Pebble Drive
Fort Worth, TX 76118

SUBJECT: VENDOR INSPECTION OF NUCLEAR LOGISTICS, INC.

Dear Mr. Seiken:

This letter documents the Nuclear Regulatory Commission (NRC) staff's plan to perform an inspection of Nuclear Logistics, Inc. to review implementation of your quality assurance program in accordance with Title 10 of the *Code of Federal Regulations* Part 50, Appendix B. Specifically, the quality assurance program will be reviewed as it pertains to Nuclear Logistics' procurement documentation and design control and testing of the 480v breaker modification for Fort Calhoun Station in 2009 that resulted in breaker fires at the Fort Calhoun Station.

As discussed during a conference call on August 1, 2012, the inspectors plan to arrive at facility, on Monday, August 27, 2012, and will conduct the inspection through Friday, August 31, 2012. Subsequent to the inspection, a report will be issued and transmitted to you via letter. The lead inspector for this effort is Mr. Douglas Bollock; you may contact him at 301-415-6609 or via electronic mail at Douglas.Bollock@nrc.gov.

The following docket number has been assigned to your facility: 999-01298. Please reference this number on any correspondence sent to the NRC.

Sincerely,

/RA/

Richard A. Rasmussen, Chief
Electrical Vendor Branch
Division of Construction Inspection
and Operational Programs
Office of New Reactors

Docket No.: 999-01298

DISTRIBUTION:

RidsNroDcipCEVB

RidsNroDcipCMVB

RidsNroDcip

ASakadales

ADAMS ACCESSION No.: ML12216A109

OFFICE	NRO/DCIP/CEVB	NRO/DCIP/CEVB
NAME	DBollock	RRasmussen
DATE	08/06/2012	08/06/2012

OFFICIAL RECORD COPY