<u>08/05/2011</u>

<u>Page 1</u>

Part 21(I	PAR)		Event a	# 47123
• -	EMERSON PROCESS MANAGEMEN FISHER CONTROLS INTERNATIONA	L Ev	ion Date / Time: 08/04/2011 ent Date / Time: 08/04/2011 st Modification: 08/04/2011	12:18 (EDT) (CDT)
Region: City: County: State:	MARSHALLTOWN	Docket #: Agreement State: License #:	Yes	
HQ Ops	ified by: BILL FITZGERALD Officer: CHARLES TEAL y Class: NON EMERGENCY Section: UNSPECIFIED PARAGRAPH	Notifications:	RONALD BELLAMY BINOY DESAI RICHARD SKOKOWSKI BOB HAGAR PART 21 GROUP	R1DO R2DO R3DO R4DO EMAIL

PART 21 - POSSIBLE WELD ROD CERTIFICATION ISSUES

"On March 3, 2011, an audit of one of Fisher Control's suppliers determined that weld rod certified by an ISO process (instead of ASME) might have been used for weld repair of castings intended for nuclear service. Fisher and the supplier are in the process of reviewing all orders affected by this issue and have yet to find any that used the subject non-confirming material

"Fisher expects to complete this evaluation by August 26, 2011. At this time, if the review determines that a failure to comply condition exits, Fisher will issue notification per the requirements of 10 CFR 21.21(b)."

IE+9 NRR

No. 2897 P. 2



Fisher Controls International LLC 301 South First Ave P.O. Box 190 Marshalltown, Iowa 50158-0190 USA T (641) 754-3011 F (641) 754-2830

August 3, 2011

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555-0001

Subject: Possible Weld Rod Certification Issues Interim Notification

Fisher Controls is providing this interim notification per the requirements of 10CFR21.21(a).

On March 3, 2011, an audit of one of Fisher Control's suppliers determined that weld rod certified by an ISO process (instead of ASME) might have been used for weld repair of castings intended for nuclear service. Fisher and the supplier are in the process of reviewing all orders affected by this issue and have yet to find any that used the subject non-conforming material.

Fisher expects to complete this evaluation by August 26, 2011. At that time, if the review determines that a failure to comply condition exists, Fisher will issue a notification per the requirements of 10CFR21.21(b).

Bill Fitzgerald Vice President, Nuclear Business Unit Emerson Process Management, Fisher Valve Division

