

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 26

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 26

---

**Facility Name: Brunswick 2 Docket (050- 00324)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	M - Mechanical	Q - Fire Protection	050-00324/2009-005
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-005
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 8</b>			
<b>Oversight / IR</b>			
130 - Inadequate suprevison / command and control	X - Site-wide	X - Site-wide	050-00324/2009-005
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	M - Mechanical	Q - Fire Protection	050-00324/2009-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-501
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-005
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00324/2009-501
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00324/2009-501
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00324/2009-005
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00324/2009-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-005
150 - Programmatic deficiency	D - Emergency Planning	D - Emergency Drill	050-00324/2009-501
150 - Programmatic deficiency	M - Mechanical	Q - Fire Protection	050-00324/2009-005
<b>Number of Items for this Docket: 10</b>			
<b>Percent of Total for this Docket: 38</b>			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	D - Emergency Planning	D - Emergency Drill	050-00324/2009-501
185 - Procedural adherence LTA	M - Mechanical	Q - Fire Protection	050-00324/2009-005
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00324/2009-501
186 - Failure to take action / meet requirements	M - Mechanical	Q - Fire Protection	050-00324/2009-005
187 - Action implementation LTA	D - Emergency Planning	G - Design	050-00324/2009-501
187 - Action implementation LTA	G - Engineering	Q - Fire Protection	050-00324/2009-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00324/2009-005
187 - Action implementation LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-005
188 - Work practice or craft skill LTA	D - Emergency Planning	M - Maintenance / Repair	050-00324/2009-501
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-501

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 26**  
**National Average: 30**  
**2x National Average: 60**  
**National Median: 18**  
**Average for Selected Dockets: 26**

---

**Facility Name: Brunswick 2 Docket (050- 00324)**

<b>Details</b>	<b>Department</b>	<b>Work Type</b>	<b>Docket/Report</b>
<b>Work Planning &amp; Practices / IR</b>			
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00324/2009-005
196 - Independent verification / plant tours LTA	M - Mechanical	Q - Fire Protection	050-00324/2009-005
197 - Self-check LTA	M - Mechanical	Q - Fire Protection	050-00324/2009-005
<b>Number of Items for this Docket: 13</b>			
<b>Percent of Total for this Docket: 50</b>			

---

**Total Items for this Docket: 26**

---