



Entergy Operations, Inc.
1448 S.R. 333
Russellville, AR 72801
Tel 501 858-5000

January 26, 2000

2CAN010008

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Station OP1-17
Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Revised Enclosure 4 Figures To Entergy Submittal 2CAN119901

Gentlemen:

On November 29, 1999, Entergy Operations, Inc. submitted proposed changes to the Arkansas Nuclear One – Unit 2 (ANO-2) Technical Specifications (TS) associated with Reactor Protective System setpoints that are affected by the steam generator replacements scheduled for the fall of 2000. These proposed changes were submitted under ANO-2 correspondence 2CAN119901 and included several analytical figures. Following submittal, it was discovered that two figures from Enclosure 4 had been superimposed. This is assumed to have occurred during electronic document conversion.


Attached are the corrected pages of Enclosure 4, 2CAN119901. Please insert these pages into your copy of 2CAN119901, Enclosure 4, as directed below:

Remove page 119
Remove page 123

Insert pages 119 and 119a
Insert pages 123 and 123a

Thank you for your assistance in this matter.

Very truly yours,



Jimmy D. Vandergrift
Director, Nuclear Safety



JDV/dbb
Attachment

Accl

cc: Mr. Ellis W. Merschoff
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

NRC Senior Resident Inspector
Arkansas Nuclear One
P.O. Box 310
London, AR 72847

Mr. Thomas Alexion
NRR Project Manager Region IV/ANO-2
U. S. Nuclear Regulatory Commission
NRR Mail Stop 04-D-3
One White Flint North
11555 Rockville Pike
Rockville, MD 20852

Mr. David D. Snellings
Director, Division of Radiation
Control and Emergency Management
Arkansas Department of Health
4815 West Markham Street
Little Rock, AR 72205

Figure 1.0.2-4
CEA Insertion vs. Time




Figure 1.4.1-1

**Loss of Condenser Vacuum
Core Power (3026 MWt Rated) vs. Time**




Figure 1.4.1-5

Loss of Condenser Vacuum
Steam Generator Pressure vs. Time





Figure 1.4.2-1

Loss of Normal Feedwater Flow
Core Power (3026 MWt Rated) vs. Time



РАСКЛАД ДИВИДЕНДОВ