

A. Alan Blind
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5718
blinda@coned.com

February 24, 2000

Re: Indian Point Unit No. 1 & No.2
Docket No. 50-03 & No. 50-247


Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

SUBJECT: 10 CFR Part 26 Semi Annual Report

In accordance with 10 CFR 26.71(d), attached is the Fitness-For-Duty Program performance data for Indian Point Station, Units No. 1 and 2, for the period July 1, 1999 through December 31, 1999.

Should you or your staff have any questions regarding this matter, please contact Mr. John McCann, Manager, Nuclear Safety and Licensing.

Very truly yours,



Attachment

cc: Mr. Hubert J. Miller
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

A021

**FITNESS FOR DUTY PROGRAM
PERFORMANCE DATA
PERSONNEL SUBJECT TO 10CFR 26**

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.		DECEMBER 31, 1999	
COMPANY		6 MONTHS ENDING	
INDIAN POINT STATION, UNITS 1 AND 2, BUCHANAN, NY 10511			
GERALD CULLEN, MANAGER, SECURITY		(914) 271-7401	
CONTACT NAME		PHONE (INCLUDE AREA CODE)	
Cut offs: Screen/Confirmation (ng/ml)		<input checked="" type="checkbox"/> Appendix A to 10CFR 26	
Marijuana	100 / 15	Amphetamines	1000 / 500
		<u>Methadone</u>	300 / 300
Cocaine	300 / 150	Phencyclidine	25 / 25
		<u>Barbiturates</u>	300 / 300
Opiates	300 / 300	Alcohol (%BAC)	0.04%
		<u>Benzodiazapine</u>	300 / 300

Testing Results		Licensee Employees		Contractor Personnel		Totals	
Average Number with Unescorted Access		632		567		1199	
Categories		# Tested	# Positive	# Tested	# Positive	# Tested	# Positive
Pre-Access		112	0	199	3	311	3
For Cause	Post Accident	0	0	0	0	0	0
	Observed	0	0	1	1	1	1
Random		224	0	101	0	325	1
Follow-Up		0	0	0	0	0	0
Other		0	0	0	0	0	0
Total		336	0	301	4	637	4

BREAKDOWN OF CONFIRMED POSITIVE TESTS FOR SPECIFIC SUBSTANCES

	Marajuana	Cocaine	Opiates	Amphetamines	Phencyclidine	Alcohol	Refusal to Test	1	2	3	4	5	
Licensee Employees	0	0	0	0	0	0	0						
Contractors	1	2	2	0	0	1	0						
													A
Totals	1	2	2	0	0	1	0						6

NOTE: Two contractors each tested positive to both cocaine and morphine (opiates).

INDIAN POINT STATION

ATTACHMENT "A"

FITNESS-FOR-DUTY SUMMARY AND MANAGEMENT ACTIONS

This report identifies Fitness-for-Duty activities at the Indian Point Station, Units 1 and 2, from July 1, 1999 to December 31, 1999. A total of 637 drug and alcohol tests were conducted during the reporting period; 311 initial or pre-access tests, 325 random tests and 1 for-cause test.

The plant population was monitored and tracked to ensure that on an annual basis random drug testing was being conducted at a rate equal to at least 50% of the total unescorted work force. The 325 random tests conducted during the reporting period, together with the 296 random tests previous reported for the first half of 1999, brought the yearly total to 621 tests. This represents a random testing rate of 51.83%, based on an annual average population of 1198 individuals with unescorted access. During this period there was an unscheduled maintenance outage from August 31, to October 16 1999.

During the July-December 1999 reporting period, a total of four (4) positive tests were recorded. Three (3) contractor employees tested positive to initial drug testing and a fourth contractor employee tested positive to alcohol as a result of a for-cause test. There were no Con Edison employees that tested positive and no random positive tests were recorded. The for-cause test resulted from security search personnel intercepting the individual prior to plant entry. All positive tests were properly recorded in the security FFD log book.

There were no instances requiring NRC notification relative to supervisors or licensed personnel testing positive to either drugs or alcohol. All three (3) contractors who tested positive to drugs, as well as the contractor who tested positive to alcohol were denied access and barred from the site.

INDIAN POINT STATION

ATTACHMENT "C"

FITNESS FOR DUTY REPORT - POSITIVE DRUG ALCOHOL TESTS

JULY 1, 1999 TO DECEMBER 31, 1999

DRUGS

AGE: Under 20	2
20 - 29	0
30 - 39	0
40 - 49	1
50 - 59	0
60 & Over	0

TOTAL **3**

ALCOHOL

AGE: Under 20	0
20 - 29	0
30 - 39	1
40 - 49	0
50 - 59	0
60 & Over	0

TOTAL **1**

DAY TESTED

DRUGS

Monday	1
Tuesday	1
Wednesday	1
Thursday	0
Friday	0
Saturday/Sunday	0

TOTAL **3**

ALCOHOL

Monday	0
Tuesday	0
Wednesday	1
Thursday	0
Friday	0
Saturday/Sunday	0

TOTAL **1**

INDIAN POINT STATION

ATTACHMENT "B"

FITNESS FOR DUTY REPORT

LICENSEE AND CONTRACTOR POSITIVE DRUG ALCOHOL TESTS

JULY 1, 1999 TO DECEMBER 31, 1999

<u>CON EDISON EMPLOYEES</u>	<u>INITIAL TEST:</u>	<u>RANDOM TEST:</u>	<u>FOR CAUSE:</u>	<u>TOTALS</u>
DRUGS:	0	0	0	0
ALCOHOL:	0	0	0	0
OTHER:	0	0	0	0
<hr/>				
TOTALS:	0	0	0	0
<u>CONTRACTOR EMPLOYEES:</u>				
DRUGS:	3	0	0	3
ALCOHOL:	0	0	1	1
OTHER:	0	0	0	0
<hr/>				
TOTALS:	3	0	1	4
GRAND TOTALS:	3	0	1	4