

A. Alan Blind
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5718
blinda@coned.com

March 13, 2000

Re: Indian Point Units
No. 1 and No. 2
Docket No. 50-003
and
No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Subject: Revision to Emergency Plan

In accordance with 10 CFR 50.54(q) and 10 CFR 50.4(b)(5), Con Edison submits herewith a controlled copy of changes to the Emergency Plan procedures for Indian Point Units Nos. 1 and 2. These changes do not reduce the effectiveness of the Emergency Plan and the Emergency Plan as a whole continues to meet the standard of 50.47(b) and the requirements of Appendix E to 10 CFR 50.

Please sign and return the controlled copy routing sheet to acknowledge receipt of these changes. Please note that the telephone numbers provided are proprietary information. Thus, in accordance with 10CFR2.790(a)(6) we understand that these documents will not be placed in the Public Document Room and will receive limited distribution.

Should you or your staff have any questions, please contact Mr. John McCann, Manager, Nuclear Safety and Licensing.

Very truly yours,

Enclosure

Charge: LRC PPR lts ewl
1 D

A045

cc: Mr. Hubert J. Miller (2 copies)
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498

Senior Resident Inspector (without copy)
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511