March 31, 2000

Mr. G. Rainey, President PECO Nuclear Nuclear Group Headquarters Correspondence Control Desk P.O. Box 195 Wayne, PA 19087-0195

SUBJECT: PLANT PERFORMANCE REVIEW - LIMERICK GENERATING STATION

The purpose of this letter is to communicate our assessment of your performance and to inform you of our planned inspections at your facility. On February 25, 2000, we completed a Plant Performance Review (PPR) of the Limerick Generating Station. We conduct these reviews to develop an integrated overview of the safety performance of each operating nuclear power plant. We use the results of the PPR in planning and allocating inspection resources and as inputs to our senior management meeting (SMM) process. This PPR evaluated inspection results and safety performance information for the period from January 16, 1999, to January 31, 2000, but emphasized the last six months to ensure that our assessment reflected your current performance. Our most recent summary of plant performance at Limerick was provided to you in a letter dated April 9, 1999, and was discussed with you in a public meeting on June 9, 1999.

The NRC has been developing a revised reactor oversight process that will replace our existing inspection and assessment processes including the PPR, the SMM, and the Systematic Assessment of Licensee Performance (SALP). We recently completed a pilot program for the revised reactor oversight process at nine participating sites and are making necessary adjustments based on feedback and lessons learned. We plan to begin initial implementation of the revised reactor oversight process industry-wide on April 2, 2000.

This PPR reflects continued NRC process improvements as we make the transition into the revised reactor oversight process. You will notice that the following summary of plant performance is organized differently from our previous performance summaries. Instead of characterizing our assessment results by SALP functional area, we are organizing the results into the strategic performance areas embodied in the revised reactor oversight process. In addition, we have considered the historical performance indicator data that you submitted in January 2000 in conjunction with the inspection results in assessing your performance. The results of this PPR were used to establish the inspection plan in accordance with the new risk-informed inspection program (consisting of baseline and supplemental inspections). Although this letter incorporates some terms and concepts associated with the new oversight process, it does not reflect the much broader changes in inspection and assessment that will be evident after we have fully implemented our revised reactor oversight process.

G. Rainey

During the last six months of the assessment period both Limerick units operated at or near full power except for five unplanned power reductions caused by equipment failures and two automatic shutdowns of Unit 2, one caused by an equipment failure and one caused by an operator error. We identified no significant performance issues in any of the strategic performance areas (reactor safety, radiation safety, and safeguards) during this assessment period and observed that Limerick continued to operate in a safe manner. Therefore, we currently plan to conduct only our normal baseline inspections at your facility as noted in the attached inspection plan.

Although we concluded that the baseline inspection program was the appropriate level of inspection, we noted some decline in equipment and human performance. We observed that equipment failures and human performance deficiencies contributed to your automatic shutdowns and unplanned power reductions. For example, one of the Unit 2 shutdowns resulted from operators not using established procedures for detecting and isolating a ground on a DC electrical distribution system. We also observed that operator errors resulted in some operational challenges, such as equipment becoming inoperable and safety equipment inadvertently starting during testing. We will monitor your progress in response to these issues during our baseline inspections.

Based on the Fourth Quarter 1999 Performance Indicator data, the availability of the Unit 1 high pressure coolant injection system was at a level that would warrant supplemental NRC inspection. However, we currently do not plan to perform any further inspection of this issue because our inspection performed in February 2000 has reviewed your evaluation and corrective actions. These findings will be documented in combined inspection report 05000352/2000-001 and 05000353/2000-001.

Enclosure 1 contains a historical listing of plant issues, referred to as the Plant Issues Matrix (PIM), that were used during this PPR process to arrive at our integrated view of your performance trends. The PIM for this assessment is grouped by the prior SALP functional areas of operations, maintenance, engineering and plant support, although the future PIM will be organized along the cornerstones of safety as described in the revised reactor oversight process. The attached PIM includes items summarized from inspection reports or other docketed correspondence between the NRC and PECO Nuclear regarding Limerick. We did not document all aspects of licensee programs and performance that may be functioning appropriately. Rather, we only documented issues that we believe warrant management attention or represent noteworthy aspects of performance. In addition, the PPR may also have considered some pre-decisional and draft material that does not appear in the attached PIM, including observations from events and inspections that had occurred since our last inspection report was issued, but had not yet received full review and consideration. We will make this material publically available as part of the normal issuance of our inspection reports and other correspondence.

Enclosure 2 lists our planned inspections for the period April 2000 through March 2001 at Limerick to allow you to resolve scheduling conflicts and personnel availability in advance of our inspector arrival onsite. Since many of the inspections at Limerick and at other Region I facilities during this period involve a team of inspectors, our ability to reschedule inspections is limited. Therefore we request that you inform us as soon as possible of any scheduling conflicts. The inspection schedule for the latter half of the period is more tentative and may be

G. Rainey

adjusted in the future due to emerging performance issues at Limerick or other Region I facilities. We also included some NRC non-inspection activities in Enclosure 2 for your information. Routine resident inspections are not listed due to their ongoing and continuous nature.

We will inform you of any changes to the inspection plan. If you have any questions, please contact me at 610-337-5233.

Sincerely,

/RA/

Curtis J. Cowgill III, Chief Reactor Projects Branch 4 Division of Reactor Projects

Docket Nos. 05000352, 05000353 License Nos. NPF-39, NPF-85

Enclosures: 1. Plant Issues Matrix 2. Inspection Plan

cc w/encl:

J. J. Hagan, Senior Vice President, Nuclear Operations Station Support

G. Edwards, Chairman, Nuclear Review Board

J. A. Hutton, Director - Licensing, PECO Nuclear

J. D. von Suskil, Vice President - Limerick Generating Station

M. P. Gallagher, Plant Manager, Limerick Generating Station

K. P. Bersticker, Manager, Experience Assessment Manager

Secretary, Nuclear Committee of the Board

Commonwealth of Pennsylvania

G. Rainey

Distribution w/encl: Region I Docket Room (with concurrences) NRC Resident Inspector Nuclear Safety Information Center (NSIC) PUBLIC H. Miller, RA J. Wiggins, DRA C. Cowgill, DRP D. Florek, DRP D. Cullison, DRP **DRS/DRP** Division Directors **DRS/DRP** Deputy Division Directors **DRP/DRS BRANCH CHIEF** J. Noggle, DRS G. Smith, DRS N. McNamara, DRS Distribution w/encl: (Via E-Mail)

J. Shea, OEDO E. Adensam, NRR J. Clifford, NRR B. Buckley, NRR W. Scott, NRR Chief, NRR/DIPM/IIPB Chief, OEDO/ROPMS DOCDESK Inspection Program Branch, NRR (IPAS)

DOCUMENT NAME: S:\February 2000 PPR\Limerick\LIM-PPR Letter rev2.wpd To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRP	RI/DRP	RI/DRP		
NAME	DFlorek	CCowgill	RCrlenjak		
DATE	03/30/00	03/30/00	03/30/00		

OFFICIAL RECORD COPY