

WATTS BAR
Inspection / Activity Plan
04/02/2000 - 03/31/2001

Units	Inspection Activity	Title	No. of Staff on Site	No. assigned to Procedure	Planned Dates Start	Planned Dates End	Inspection Type
	PS-RP	- RADIATION PROTECTION	1				
1	IP 7112101	Access Control to Radiologically Significant Areas		1	06/12/2000	06/16/2000	Baseline Inspections
	PB6-PI&R	- PROBLEM IDENTIFICATION & RESOLUTION	3				
1	IP 71152	Identification and Resolution of Problems		3	07/10/2000	07/14/2000	Baseline Inspections
	OL-RQ	- REQUAL INSPECTION	1				
1	IP 7111111B	Licensed Operator Requalification		1	07/24/2000	07/28/2000	Baseline Inspections
	PB6-PI&R	- PROBLEM IDENTIFICATION & RESOLUTION	3				
1	IP 71152	Identification and Resolution of Problems		3	07/24/2000	07/28/2000	Baseline Inspections
	PS-ALARA	- ALARA PLANNING & CONTROLS	1				
1	IP 7112102	ALARA Planning and Controls		1	07/31/2000	08/04/2000	Baseline Inspections
	PB6LAYUP	- U2 CONSTR LAYUP	1				
1	IP 92050	Review Of Quality Assurance For Extended Construction Delays		1	08/07/2000	08/11/2000	Supplemental Program
	PS-RP	- RADIATION PROTECTION	1				
1	IP 7112202	Radioactive Material Processing and Transportation		1	08/14/2000	08/18/2000	Baseline Inspections
	OL-EP	- EMERGENCY PREPAREDNESS	1				
1	IP 7111402	Alert and Notification System Testing		1	08/21/2000	08/25/2000	Baseline Inspections
1	IP 7111403	Emergency Response Organization Augmentation Testing		1	08/21/2000	08/25/2000	Baseline Inspections
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		1	08/21/2000	08/25/2000	Baseline Inspections
1	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		1	08/21/2000	08/25/2000	Baseline Inspections
	PS-ALARA	- ALARA PLANNING & CONTROLS	1				
1	IP 7112102	ALARA Planning and Controls		1	09/11/2000	09/15/2000	Baseline Inspections
	MB-ISI	- U1-ISI	1				
1	IP 7111108	Inservice Inspection Activities		1	09/25/2000	09/29/2000	Baseline Inspections
	EB-FP	- FIRE PROTECTION PREP	5				
1	IP 7111105T	Fire Protection		1	10/30/2000	11/03/2000	Baseline Inspections
	PS-SEC	- SECURITY	1				
1	IP 7113001	Access Authorization Program (Behavior Observation Only)		1	10/30/2000	11/03/2000	Baseline Inspections
1	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and		1	10/30/2000	11/03/2000	Baseline Inspections
1	IP 71151	Performance Indicator Verification		1	10/30/2000	11/03/2000	Baseline Inspections
	MB-50.59	- 10 CFR 50.59	1				
1	IP 7111102	Evaluation of Changes, Tests, or Experiments		1	11/13/2000	11/17/2000	Baseline Inspections
	EB-FP	- FIRE PROTECTION	4				
1	IP 7111105T	Fire Protection		3	12/04/2000	12/08/2000	Baseline Inspections
	OL-PREP	- INITIAL EXAM PREP	2				
1	V23161	WATTS BARR 1/INITIAL EXAMS AT POWER FACILITIES		2	01/08/2001	01/12/2001	Not Applicable

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

WATTS BAR
Inspection / Activity Plan
04/02/2000 - 03/31/2001

Units	Inspection Activity	Title	No. of Staff on Site	No. assigned to Procedure	Planned Dates		Inspection Type
					Start	End	
	PS-RP	- RADIATION PROTECTION	1				
1	IP 7112103	Radiation Monitoring Instrumentation		1	01/08/2001	01/12/2001	Baseline Inspections
1	IP 71151	Performance Indicator Verification		1	01/08/2001	01/12/2001	Baseline Inspections
	OL EXAM	- INITIAL-EXAM	2				
1	V23161	WATTS BARR 1/INITIAL EXAMS AT POWER FACILITIES		2	01/22/2001	02/02/2001	Not Applicable
	PS-RP	- RADIATION PROTECTION	1				
1	IP 7112203	Radiological Environmental Monitoring Program		1	03/26/2001	03/30/2001	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.