

A. Alan Blind
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5718
blinda@coned.com

April 10, 2000

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555-0001

Subject: Incorporation of Code Case N-496-1 into Inservice Inspection
Program

Con Edison, effective immediately, is implementing ASME Code Case N-496-1 for the third ten-year interval of the Indian Point Unit 2 Inservice Inspection (ISI) Program, which extends until May 18, 2005.

NRC endorsement of Code Case N-496-1, "Helical-Coil Threaded Inserts Section XI, Division 1," dated May 11, 1994, is documented within Regulatory Guide 1.147 Revision 12.

No new regulatory commitments are being made by Con Edison in this correspondence.

Should you or your staff have any concerns regarding this matter, please contact Mr. John McCann, Manager, Nuclear Safety & Licensing.

Very truly yours,

A. Alan Blind

AD47 1/0

C: Mr. Hubert J. Miller
Regional Administrator-Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager
Project directorate I-1
Division of Regulatory Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511