

PECO Energy Company PO Box 2300 Sanatoga, PA 19464-0920

T.S.6.9.1.6

May 5, 2000

Docket Nos. 50-352 50-353 License Nos. NPF-39 NPF-85

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Subject: Limerick Generating Station Monthly Operating Report For Units 1 and 2

Enclosed are the monthly operating reports for Limerick Units 1 and 2 for the month of April 2000 forwarded pursuant to Technical Specification 6.9.1.6.

Very truly yours,

Mark aldefa for CBA

Caren B. Anders Director - Site Engineering

pah

Enclosures

- cc: H. J. Miller, Administrator, Region I, USNRC A. L. Burritt, USNRC Senior Resident Inspector LGS
 - J. D. von Suskil, Vice President, LGS
 - S. T. Gamble, LGS Experience Assessment Branch, SSB2-4
 - S. A. Auve, LGS ISEG Branch, SSB4-2

JE24

Docket No. 50-352 Attachment to Monthly Operating Report for April 2000

Limerick Generating Station Unit 1 April 1 through April 30, 2000

I. Narrative Summary of Operating Experiences

Unit 1 began the month of April 2000 at 0% of rated thermal power with 1R08 refuel outage in progress.

On April 24, 2000 at 1229, the reactor mode switch was placed in startup.

On April 24, 2000 at 1751 hours, reactor criticality was achieved during start-up from 1R08 refuel outage. Power ascension proceeded.

On April 28, 2000 at 1040 hours, the main generator was synchronized to the grid at 22% of RTP. On April 28, 2000 at 1418 hours, the main generator was resynchronized to the grid at 22% of RTP following satisfactory overspeed testing.

On April 30, 2000 at 0600 hours, the unit reached 100% of RTP. Recirc flow was maximized, and core thermal power was allowed to decrease so that xenon could "build in" to the core.

Unit 1 ended the month of April 2000 at 91% RTP with xenon still "building in" to the core.

II. Challenges to Main Steam Safety Relief Valves

There were no challenges to the Main Steam Safety Relief Valves during the month of April. There have been no challenges to the Main Steam Safety Relief Valves year-to-date.

DOCKET NO.50-352DATEMAY 5, 2000COMPLETED BYPECO ENERGY COMPANYP. A. HINCHEYTHERMAL PERFORMANCE ENGINEERSITE ENGINEERINGLIMERICK GENERATING STATIONTELEPHONE(610) 718-3797

OPERATING STATUS

| 1. UNIT NAME: | LIMERICK UNIT 1 |
|---|-----------------|
| 2. REPORTING PERIOD: | APRIL 2000 |
| 3. DESIGN ELECTRICAL RATING: | 1134 |
| 4. MAXIMUM DEPENDABLE CAPACITY (GROSS MWE): | 1174 |
| 5. MAXIMUM DEPENDABLE CAPACITY (NET MWE): | 1134 |

| | THIS MONTH | YR-TO-DATE | CUMULATIVE |
|---|------------|------------|-------------|
| | | | |
| 6. NUMBER OF HOURS REACTOR WAS CRITICAL | 150.2 | 2.278.0 | 106,984.6 |
| 0. NUMBER OF HOURS REACTOR WAS CRITICAL | 150.2 | 2,278.0 | 100,904.0 |
| 7. REACTOR RESERVE SHUTDOWN HOURS | 0.0 | 0.0 | 0.0 |
| 8. HOURS GENERATOR ON-LINE | 60.2 | 2,187.1 | 105,131.7 |
| 9. UNIT RESERVE SHUTDOWN HOURS | 0.0 | 0.0 | 0.0 |
| 10. NET ELECTRICAL ENERGY GENERATED (MWH) | 38,465 | 2,383,036 | 105,736,735 |

| | | | | | с | DATE | LIMERICK UNIT 1 MAY 5, 2000 PECO ENERGY COMPANY P. A. HINCHEY |
|-----|--------|-------------|---------------------|---------------|--|-----------|---|
| | | | | | | | THERMAL PERFORMANCE ENGINEER SITE ENGINEERING LIMERICK GENERATING STATION |
| | | | APRIL 2000 | | | TELEPHONE | (610) 718-3797 |
| NO. | DATE | TYPE (1) | DURATION (HOURS) | REASON (2) | METHOD OF SHUTTING DOWN REACTOR (3) | | CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE |
| 352 | 000329 | S | 658.8 | С | 1 | | Refuel Outage IR08 |

| (1) |
|-------------|
| Туре |
| F Forced |
| S Scheduled |

(2) Reason

A -- Equipment Failure

B -- Maintenance or Test

C -- Refueling

- D -- Regulatory Restriction
- E -- Operational Training & License Examination

F -- Administrative

- G -- Operational Error (Explain)
- H -- Other (Explain)

(3)

1

Method

1 -- Manual

- 2 -- Manual Scram
- 3 -- Automatic Scram
- 4 -- Other (Explain)

Docket No. 50-353 Attachment to Monthly Operating Report for April 2000

Limerick Generating Station Unit 2 April 1 through April 30, 2000

I. Narrative Summary of Operating Experiences

Unit 2 began the month of April 2000 at 100% of rated thermal power (RTP).

On April 30th at 1148 reactor power was reduced to 98% RTP for a control rod pattern adjustment. Reactor power was returned to 100% RTP on April 30th at 1200.

Unit 2 ended the month of April 2000 at 100% of rated thermal power.

II. Challenges to Main Steam Safety Relief Valves

There were no challenges to the Main Steam Safety Relief Valves during the month of April. There have been no challenges to the Main Steam Safety Relief Valves year-to-date.

DOCKET NO. 50-353 DATE MAY 5, 2000 COMPLETED BY PECO ENERGY COMPANY P. A. HINCHEY THERMAL PERFORMANCE ENGINEER SITE ENGINEERING LIMERICK GENERATING STATION TELEPHONE (610) 718-3797

OPERATING STATUS

| 1. UNIT NAME: | LIMERICK UNIT 2 |
|---|-----------------|
| 2. REPORTING PERIOD: | APRIL 2000 |
| 3. DESIGN ELECTRICAL RATING: | 1150 |
| 4. MAXIMUM DEPENDABLE CAPACITY (GROSS MWE): | 1190 |
| 5. MAXIMUM DEPENDABLE CAPACITY (NET MWE): | 1150 |

| | THIS MONTH | YR-TO-DATE | CUMULATIVE |
|---|------------|------------|------------|
| | | | |
| 6. NUMBER OF HOURS REACTOR WAS CRITICAL | 719.0 | 2,839.6 | 83,251.7 |
| 7. REACTOR RESERVE SHUTDOWN HOURS | 0.0 | 0.0 | 0.0 |
| 8. HOURS GENERATOR ON-LINE | 719.0 | 2,780.5 | 81,650.8 |
| 9. UNIT RESERVE SHUTDOWN HOURS | 0.0 | 0.0 | 0.0 |
| 10. NET ELECTRICAL ENERGY GENERATED (MWH) | 842,449 | 3,217,687 | 85,648,335 |

| NO. | DATE | TYPE (1) | DURATION (HOURS) | REASON (2) | METHOD OF SHUTTING DOWN REACTOR (3) | | CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE | |
|-----|----------|-------------|---------------------|---------------|--|--------------|--|--|
| | REPORT M | ONTH | APRIL 2000 | | C | COMPLETED BY | LIMERICK UNIT 2 MAY 5, 2000 | |

(1)

Type F -- Forced

S -- Scheduled

- (2) Reason
- A -- Equipment Failure
- B -- Maintenance or Test
- C -- Refueling
- D -- Regulatory Restriction
- E -- Operational Training & License Examination
- F -- Administrative
- G -- Operational Error (Explain)
- H -- Other (Explain)

(3)

- Method
- 1 -- Manual
- 2 -- Manual Scram
- 3 -- Automatic Scram

1

4 -- Other (Explain)