



Carolina Power & Light Company
Harris Nuclear Plant
PO Box 165
New Hill NC 27562

MAY 6 2000

SERIAL: HNP-00-085

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT
DOCKET NO. 50-400/LICENSE NO. NPF-63
15 DAY SPECIAL REPORT - STEAM GENERATOR TUBES PLUGGED

Dear Sir or Madam:

In accordance with Technical Specification 4.4.5.5.a for the Harris Nuclear Plant, Carolina Power & Light Company is providing the enclosed Special Report. This report identifies the number of steam generator tubes plugged as a result of the recent Steam Generator Tube Inservice Inspection conducted during Refueling Outage No. 9.

The complete results of the Steam Generator Tube Inservice Inspection will be submitted to the NRC within 12 months of completion as required by Technical Specification 4.4.5.5.b.

Questions regarding this submittal may be referred to Mr. E. A. McCartney at (919) 362-2661.

Sincerely,

D. B. Alexander
Manager, Regulatory Affairs
Harris Nuclear Plant

MGW

Enclosure

- c: Mr. J. B. Brady (NRC Senior Resident Inspector, HNP)
Mr. R. J. Laufer (NRR Project Manager, HNP)
Mr. L. A. Reyes (NRC Regional Administrator, Region II)

HARRIS NUCLEAR PLANT
SPECIAL REPORT

STEAM GENERATOR TUBE INSERVICE INSPECTION (RFO9)
NUMBER OF TUBES PLUGGED

| <u>Steam Generator</u> | <u>A</u> | <u>B</u> | <u>C</u> |
|---------------------------|----------|----------|----------|
| Current (RFO9 only) | 3 | 12 | 29 |
| Cumulative (through RFO9) | 77 | 44 | 87 |