

August 31, 2000

FACILITY: INDIAN POINT NUCLEAR GENERATING UNIT NO. 2

LICENSEE: CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.

SUBJECT: SUMMARY OF MAY 3, 2000, MEETING BETWEEN CONSOLIDATED EDISON COMPANY OF NEW YORK, INC. (CON ED) AND NRC STAFF CONCERNING REVIEW OF INDIAN POINT 2 STEAM GENERATOR ISSUES (TAC NO. MA8219)

The Nuclear Regulatory Commission (NRC) met with Con Ed on May 3, 2000, at the NRC offices in Rockville, Maryland. The purpose of the meeting was to discuss technical matters associated with the IP2 February 15, 2000, steam generator tube failure event. Specifically, the NRC staff focused on Con Ed's April 14, 2000, root cause analysis and concerns associated with the condition monitoring and operational assessment. The NRC staff has also published several questions by letter dated April 28, 2000, that were addressed by Con Ed.

After introductory remarks from the NRC staff, Con Ed provided four presentations to the staff. The presentations were as follows: Root Cause Analysis report overview, Indian Point Unit 2 Low Row U-bend Examinations, U-Bend pressurized water stress corrosion cracking Susceptibility Investigation, and Indian Point 2 Condition Monitoring Operational Assessment Plan. At the conclusion of the meeting, NRC staff remained and answered questions regarding the staff's review effort with members of the public. Enclosure 1 is a list of attendees at the meeting. The meeting was transcribed, and a copy of the transcription and the handouts distributed during the meeting are Enclosure 2.

Please direct any inquires concerning this meeting to me. I can be reached at (301) 415-1421 or [JFH@NRC.GOV](mailto:JFH@NRC.GOV).

**/RA/**

Jefferey F. Harold, Project Manager  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-247

Enclosures: As stated

cc w/encls: See next page

August 31, 2000

FACILITY: INDIAN POINT NUCLEAR GENERATING UNIT NO. 2

LICENSEE: CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.

SUBJECT: SUMMARY OF MAY 3, 2000, MEETING BETWEEN CONSOLIDATED EDISON COMPANY OF NEW YORK, INC. (CON ED) AND NRC STAFF CONCERNING REVIEW OF INDIAN POINT 2 STEAM GENERATOR ISSUES (TAC NO. MA8219)

The Nuclear Regulatory Commission (NRC) met with Con Ed on May 3, 2000, at the NRC offices in Rockville, Maryland. The purpose of the meeting was to discuss technical matters associated with the IP2 February 15, 2000, steam generator tube failure event. Specifically, the NRC staff focused on Con Ed's April 14, 2000, root cause analysis and concerns associated with the condition monitoring and operational assessment. The NRC staff has also published several questions by letter dated April 28, 2000, that were addressed by Con Ed.

After introductory remarks from the NRC staff, Con Ed provided four presentations to the staff. The presentations were as follows: Root Cause Analysis report overview, Indian Point Unit 2 Low Row U-bend Examinations, U-Bend pressurized water stress corrosion cracking Susceptibility Investigation, and Indian Point 2 Condition Monitoring Operational Assessment Plan. At the conclusion of the meeting, NRC staff remained and answered questions regarding the staff's review effort with members of the public. Enclosure 1 is a list of attendees at the meeting. The meeting was transcribed, and a copy of the transcription and the handouts distributed during the meeting are Enclosure 2.

Please direct any inquires concerning this meeting to me. I can be reached at (301) 415-1421 or [JFH@NRC.GOV](mailto:JFH@NRC.GOV).

**/RA/**

Jefferey F. Harold, Project Manager  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-247

Enclosures: As stated

cc w/encls: See next page

**DISTRIBUTION:**

PUBLIC	E. Adensam	E. Murphy	U. Bhachu
PDI-1 R/F	M. Gamberoni	S. Coffin	J. Muscara
B. Sheron	J. Harold	D. Kalinovsky	S. Long
T. Sullivan	P. Milano	S. Little	D. Wessman
J. Zwolinski	ACRS	J. Strosnider	E. Benner
S. Black	OGC	J. Minns	J. Hopenfeld
W. Bateman	A. Lund		

Accession Number: ML003736169

OFC	PM:PDI-1	LA:PDI-1	SC:PDI-1
NAME	JHarold	SLittle	MGamberoni
DATE	8/7/00	8/3/00	8/30/00

OFFICIAL RECORD COPY

Indian Point Nuclear Generating Station  
Units 1½

Mayor, Village of Buchanan  
236 Tate Avenue  
Buchanan, NY 10511

Mr. F. William Valentino, President  
New York State Energy, Research,  
and Development Authority  
Corporate Plaza West  
286 Washington Ave. Extension  
Albany, NY 12203-6399

Mr. John McCann  
Manager of Nuclear Safety and  
Licensing  
Consolidated Edison Company  
of New York, Inc.  
Broadway and Bleakley Avenue  
Buchanan, NY 10511

Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P.O. Box 38  
Buchanan, NY 10511

Mr. Brent L. Brandenburg  
Assistant General Counsel  
Consolidated Edison Company  
of New York, Inc.  
4 Irving Place - 1822  
New York, NY 10003

David Lochbaum  
Nuclear Safety Engineer  
Union of Concerned Scientists  
1616 P Street, NW., Suite 310  
Washington, DC 20036

Edward Smeloff  
Pace University School of Law  
The Energy Project  
78 North Broadway  
White Plains, NY 10603

Charles Donaldson, Esquire  
Assistant Attorney General  
New York Department of Law  
120 Broadway  
New York, NY 10271

Ms. Charlene D. Faison, Director  
Nuclear Licensing  
Power Authority of the State  
of New York  
123 Main Street  
White Plains, NY 10601

Mr. Thomas Rose  
Secretary - NFSC  
Consolidated Edison Company  
of New York, Inc.  
Broadway and Bleakley Avenue  
Buchanan, NY 10511

Regional Administrator, Region I  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Paul Eddy  
New York State Department of  
Public Service  
3 Empire State Plaza, 10th Floor  
Albany, NY 12223

Mr. A. Alan Blind  
Vice President, Nuclear Power  
Consolidated Edison Company  
of New York, Inc.  
Broadway and Bleakley Avenue  
Buchanan, NY 10511

Jim Riccio  
Public Citizen's Critical Mass Energy Project  
215 Pennsylvania Ave., SE  
Washington, DC 20003

Michael Mariotte  
Nuclear Information & Resources Service  
1424 16<sup>th</sup> Street, NW, Suite 404  
Washington, DC 20036