



OVERNIGHT DELIVERY

50-280/281

August 24, 2000

Ms. Tia Chambers, Asbestos Coordinator (3WC32)
U. S. Environmental Protection Agency
Region III
1650 Arch Street
Philadelphia, Pennsylvania 19103

Dear Ms. Chambers:

This letter is being submitted pursuant to 40 CFR 61.150 (d)(4) and in accordance with your letter dated July 1, 1994 confirming that Virginia Power's procedure for tracking low-level radiologically contaminated asbestos waste (RCAW) is acceptable for maintaining compliance with the National Emissions Standards for Hazardous Air Pollutants (NESHAP) regulations. This is official notification that Surry Power Station (1) has not received a copy of a waste shipment record (WSR), signed by the owner or operator of the designated waste disposal site within 35 days since the waste was shipped off-site (inquiry requirement time period) and (2) will not receive the WSR within 45 days (notification requirement time period).

On July 11, 2000, RCAW (Shipment G2000-6) was shipped from Surry Power Station to GTS Duratek and was received by GTS Duratek on July 12, 2000 (a copy of the asbestos WSR and GTS Duratek's receipt notification are attached for your review). Once the interim process is complete, the waste will be shipped to either Barnwell Waste Management Facility in Barnwell, South Carolina for final burial (see Line 3) or shipped to another licensed facility for burial. The interim process is taking longer than expected and the signed WSR was not returned to Surry Power Station within 35 days. Therefore, a search was initiated to determine the status of the waste shipment.


On August 15, 2000, the 35th day, Surry Power Station inquired to GTS Duratek about shipment G2000-6 and was informed by GTS Duratek in a telephone conversation that the waste shipment will be processed after the 35th day and will not be buried until after August 25, 2000, the required 45th reporting date. The waste shipment is still located at GTS Duratek. A copy of a written notification dated July 12, 2000, from GTS Duratek to Surry Power Station was forwarded to Virginia Power's Environmental Policy and Compliance (EP&C) Department and is attached for your review.

Once Surry Power Station receives the waste shipment records, the EP&C Department will be notified and then will notify the EPA that the outstanding WSR has been received and closed.

ADD 1

If you have any questions or concerns, please do not hesitate to contact Russ Wood at (804) 273-3015 or Annette Christian at (804) 273-2988 of our Environmental Policy and Compliance Department.

Very truly yours,

A handwritten signature in black ink that reads "Pamela F. Faggert". The signature is written in a cursive, flowing style.

Pamela F. Faggert
Vice-President and Chief Environmental Officer

Enclosures

cc: U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555
RE: Surry Units 1 and 2
Docket Nos. 50-280 and 50-281
License Nos. DPR-32 and DPR-37

Surry Power Station
Units 1 and 2
Docket Nos. 50-280 and 50-281
License Nos. DPR-32 and DPR-37

ATTACHMENT 7

(Page 1 of 1)

ASBESTOS WASTE SHIPMENT RECORD

GENERATOR		
1. Work site name and mailing address Surry Power Station, 5570 Hog Island Rd. Surry, Virginia 23883	Owner's name Virginia Power Owner's telephone number (757)365-2010	Shipment Number G 2000 - 6
2. Operator's name and address Insulation Specialties, Inc. P.O. Box 127, 501 Westover Ave., Hopewell, VA 23860		Operator's telephone number (804) 458-1555
3. Waste Disposal Site (WDS) name, mailing address, and physical site location Barnwell Waste Management Facility P. O. Box 726, Barnwell, South Carolina 29812		WDS telephone number (803) 259-1781
4. Name, and address of responsible agency Department of Labor and Industry, 13 South Thirteenth Street, Richmond, Virginia 23219		
5. Description of materials Radioactive material, LSA, b.o.s., 7, UN 2912 Friable Pipe Covering	6. Containers no. and type (1) B-25 Box containing "BA" (bags)	7. Total quantity m ³ (yd ³) 2.55 m ³
8. Special handling instructions and additional information For shipment to intermediate processor: GTS Dumtek 1560 Bear Creek Road Oak Ridge, TN 37831-2530 Telephone: (423) 481-0222		
9. OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name, are classified, packed, marked, labeled, and are in all respects in proper condition for transport by highway according to applicable international and government regulations.		
Printed or typed name and title Edward L. Mcomber Jr Foreman	Signature Edward L. Mcomber Jr	Month Day Year 07 11 00
TRANSPORTER		
10. Transporter 1 (acknowledgment of receipt of materials)		
Printed or typed name and title Jack Gilmore	Signature Jack Gilmore	Month Day Year 7 11 2000
Address 1560 Bear Creek Rd, Oak Ridge, TN 3783-2530		Telephone number 1-800-418-9676
11. Transporter 2 (acknowledgment of receipt of materials)		
Printed or typed name and title	Signature	Month Day Year
Address		Telephone number
DISPOSAL SITE		
12. Discrepancy indication space		
13. Waste disposal site owner or operator: Certification of receipt of asbestos materials covered by this manifest except as noted in item 12.		
Printed or typed name and title	Signature	Month Day Year

Wednesday, July 12, 2000

Ron Spivey
Virginia Power/Surry
5570 Hog Island Road
Surry, VA 23883

Dear Mr. Spivey:

In compliance with the requirements of 10 CFR 20, Appendix G, Section III, C.1, the attached signed shipping manifest copies are your notice of receipt and acceptance of the radioactive waste materials specified on the manifests.

Manifest Number	Date Received
241-G2000-6	07/12/2000

This is acknowledgement of receipt only. Any manifest discrepancies found during manifest review, unloading or processing will be listed on page 2 of this letter.

Thank you for your business.

Sincerely,



Shipping and Receiving

cc: Manifest File
Shipping and Receiving file

Asbestos

Manifest Discrepancies

None.

**UNIFORM LOW-LEVEL RADIOACTIVE
WASTE MANIFEST
SHIPPING PAPER**

U.S. NUCLEAR REGULATORY COMMISSION
 (757) 365-2353, 367-7281

1. EMERGENCY TELEPHONE NUMBER (Include Area Code)
 ORGANIZATION: VIRGINIA POWER

2. IS THIS AN EXCLUSIVE USE SHIPMENT?
 YES NO

3. TOTAL NUMBER OF PACKAGES IDENTIFIED ON THIS MANIFEST: 14

4. DOES EPA REGULATED WASTE REQUIRING A MANIFEST ACCOMPANY THIS SHIPMENT? YES NO

5. SHIPPER - Name and Address
 SURREY POWER STATION
 VIRGINIA POWER
 5570 HOG ISLAND ROAD
 SURREY, VA - 23883

6. CARRIER - Name and Address
 HITTMAN TRANSPORT
 1580 BEAR CREEK RD.
 OAK RIDGE, TN 37831

7. FORM 540 AND 541A, 541B, 541C, 541D, 541E, 541F, 541G, 541H, 541I, 541J, 541K, 541L, 541M, 541N, 541O, 541P, 541Q, 541R, 541S, 541T, 541U, 541V, 541W, 541X, 541Y, 541Z, 541AA, 541AB, 541AC, 541AD, 541AE, 541AF, 541AG, 541AH, 541AI, 541AJ, 541AK, 541AL, 541AM, 541AN, 541AO, 541AP, 541AQ, 541AR, 541AS, 541AT, 541AU, 541AV, 541AW, 541AX, 541AY, 541AZ, 541BA, 541BB, 541BC, 541BD, 541BE, 541BF, 541BG, 541BH, 541BI, 541BJ, 541BK, 541BL, 541BM, 541BN, 541BO, 541BP, 541BQ, 541BR, 541BS, 541BT, 541BU, 541BV, 541BW, 541BX, 541BY, 541BZ, 541CA, 541CB, 541CC, 541CD, 541CE, 541CF, 541CG, 541CH, 541CI, 541CJ, 541CK, 541CL, 541CM, 541CN, 541CO, 541CP, 541CQ, 541CR, 541CS, 541CT, 541CU, 541CV, 541CW, 541CX, 541CY, 541CZ, 541DA, 541DB, 541DC, 541DD, 541DE, 541DF, 541DG, 541DH, 541DI, 541DJ, 541DK, 541DL, 541DM, 541DN, 541DO, 541DP, 541DQ, 541DR, 541DS, 541DT, 541DU, 541DV, 541DW, 541DX, 541DY, 541DZ, 541EA, 541EB, 541EC, 541ED, 541EE, 541EF, 541EG, 541EH, 541EI, 541EJ, 541EK, 541EL, 541EM, 541EN, 541EO, 541EP, 541EQ, 541ER, 541ES, 541ET, 541EU, 541EV, 541EW, 541EX, 541EY, 541EZ, 541FA, 541FB, 541FC, 541FD, 541FE, 541FF, 541FG, 541FH, 541FI, 541FJ, 541FK, 541FL, 541FM, 541FN, 541FO, 541FP, 541FQ, 541FR, 541FS, 541FT, 541FU, 541FV, 541FW, 541FX, 541FY, 541FZ, 541GA, 541GB, 541GC, 541GD, 541GE, 541GF, 541GG, 541GH, 541GI, 541GJ, 541GK, 541GL, 541GM, 541GN, 541GO, 541GP, 541GQ, 541GR, 541GS, 541GT, 541GU, 541GV, 541GW, 541GX, 541GY, 541GZ, 541HA, 541HB, 541HC, 541HD, 541HE, 541HF, 541HG, 541HH, 541HI, 541HJ, 541HK, 541HL, 541HM, 541HN, 541HO, 541HP, 541HQ, 541HR, 541HS, 541HT, 541HU, 541HV, 541HW, 541HX, 541HY, 541HZ, 541IA, 541IB, 541IC, 541ID, 541IE, 541IF, 541IG, 541IH, 541II, 541IJ, 541IK, 541IL, 541IM, 541IN, 541IO, 541IP, 541IQ, 541IR, 541IS, 541IT, 541IU, 541IV, 541IW, 541IX, 541IY, 541IZ, 541JA, 541JB, 541JC, 541JD, 541JE, 541JF, 541JG, 541JH, 541JI, 541JJ, 541JK, 541JL, 541JM, 541JN, 541JO, 541JP, 541JQ, 541JR, 541JS, 541JT, 541JU, 541JV, 541JW, 541JX, 541JY, 541JZ, 541KA, 541KB, 541KC, 541KD, 541KE, 541KF, 541KG, 541KH, 541KI, 541KJ, 541KK, 541KL, 541KM, 541KN, 541KO, 541KP, 541KQ, 541KR, 541KS, 541KT, 541KU, 541KV, 541KW, 541KX, 541KY, 541KZ, 541LA, 541LB, 541LC, 541LD, 541LE, 541LF, 541LG, 541LH, 541LI, 541LJ, 541LK, 541LL, 541LM, 541LN, 541LO, 541LP, 541LQ, 541LR, 541LS, 541LT, 541LU, 541LV, 541LW, 541LX, 541LY, 541LZ, 541MA, 541MB, 541MC, 541MD, 541ME, 541MF, 541MG, 541MH, 541MI, 541MJ, 541MK, 541ML, 541MN, 541MO, 541MP, 541MQ, 541MR, 541MS, 541MT, 541MU, 541MV, 541MW, 541MX, 541MY, 541MZ, 541NA, 541NB, 541NC, 541ND, 541NE, 541NF, 541NG, 541NH, 541NI, 541NJ, 541NK, 541NL, 541NM, 541NO, 541NP, 541NQ, 541NR, 541NS, 541NT, 541NU, 541NV, 541NW, 541NX, 541NY, 541NZ, 541OA, 541OB, 541OC, 541OD, 541OE, 541OF, 541OG, 541OH, 541OI, 541OJ, 541OK, 541OL, 541OM, 541ON, 541OO, 541OP, 541OQ, 541OR, 541OS, 541OT, 541OU, 541OV, 541OW, 541OX, 541OY, 541OZ, 541PA, 541PB, 541PC, 541PD, 541PE, 541PF, 541PG, 541PH, 541PI, 541PJ, 541PK, 541PL, 541PM, 541PN, 541PO, 541PP, 541PQ, 541PR, 541PS, 541PT, 541PU, 541PV, 541PW, 541PX, 541PY, 541PZ, 541QA, 541QB, 541QC, 541QD, 541QE, 541QF, 541QG, 541QH, 541QI, 541QJ, 541QK, 541QL, 541QM, 541QN, 541QO, 541QP, 541QQ, 541QR, 541QS, 541QT, 541QU, 541QV, 541QW, 541QX, 541QY, 541QZ, 541RA, 541RB, 541RC, 541RD, 541RE, 541RF, 541RG, 541RH, 541RI, 541RJ, 541RK, 541RL, 541RM, 541RN, 541RO, 541RP, 541RQ, 541RR, 541RS, 541RT, 541RU, 541RV, 541RW, 541RX, 541RY, 541RZ, 541SA, 541SB, 541SC, 541SD, 541SE, 541SF, 541SG, 541SH, 541SI, 541SJ, 541SK, 541SL, 541SM, 541SN, 541SO, 541SP, 541SQ, 541SR, 541SS, 541ST, 541SU, 541SV, 541SW, 541SX, 541SY, 541SZ, 541TA, 541TB, 541TC, 541TD, 541TE, 541TF, 541TG, 541TH, 541TI, 541TJ, 541TK, 541TL, 541TM, 541TN, 541TO, 541TP, 541TQ, 541TR, 541TS, 541TT, 541TU, 541TV, 541TW, 541TX, 541TY, 541TZ, 541UA, 541UB, 541UC, 541UD, 541UE, 541UF, 541UG, 541UH, 541UI, 541UJ, 541UK, 541UL, 541UM, 541UN, 541UO, 541UP, 541UQ, 541UR, 541US, 541UT, 541UU, 541UV, 541UW, 541UX, 541UY, 541UZ, 541VA, 541VB, 541VC, 541VD, 541VE, 541VF, 541VG, 541VH, 541VI, 541VJ, 541VK, 541VL, 541VM, 541VN, 541VO, 541VP, 541VQ, 541VR, 541VS, 541VT, 541VU, 541VV, 541VW, 541VX, 541VY, 541VZ, 541WA, 541WB, 541WC, 541WD, 541WE, 541WF, 541WG, 541WH, 541WI, 541WJ, 541WK, 541WL, 541WM, 541WN, 541WO, 541WP, 541WQ, 541WR, 541WS, 541WT, 541WU, 541WV, 541WW, 541WX, 541WY, 541WZ, 541XA, 541XB, 541XC, 541XD, 541XE, 541XF, 541XG, 541XH, 541XI, 541XJ, 541XK, 541XL, 541XM, 541XN, 541XO, 541XP, 541XQ, 541XR, 541XS, 541XT, 541XU, 541XV, 541XW, 541XX, 541XY, 541XZ, 541YA, 541YB, 541YC, 541YD, 541YE, 541YF, 541YG, 541YH, 541YI, 541YJ, 541YK, 541YL, 541YM, 541YN, 541YO, 541YP, 541YQ, 541YR, 541YS, 541YT, 541YU, 541YV, 541YW, 541YX, 541YY, 541YZ, 541ZA, 541ZB, 541ZC, 541ZD, 541ZE, 541ZF, 541ZG, 541ZH, 541ZI, 541ZJ, 541ZK, 541ZL, 541ZM, 541ZN, 541ZO, 541ZP, 541ZQ, 541ZR, 541ZS, 541ZT, 541ZU, 541ZV, 541ZW, 541ZX, 541ZY, 541ZZ

8. CONSIGNEE - Name and Facility Address
 018 Dunbar Bear Creek Inc.
 Central Volume Reduction Facility
 1580 Bear Creek Rd.
 Oak Ridge, TN 37830

9. CONTACT
 Karen KERRY
 (615) 461-0272

10. CERTIFICATION
 I certify that the materials are properly classified, described, packaged, marked, and labeled and in proper condition for transportation according to the applicable regulations of the Department of Transportation. This also certifies that the materials are identified, packaged, marked, and labeled and are in proper condition for transportation and disposal as described in accordance with the applicable requirements of 10 CFR Parts 26 and 61, or equivalent state regulations.

11. U.S. DEPARTMENT OF TRANSPORTATION DESCRIPTION (including proper shipping name, hazard class, UN ID number, and any additional information)
 Radioactive Material, LSA, n.l.s., 7, UN2912
 Plutonium Excepted
 OADR

12. DOT LABEL RADIOACTIVE
 N/A

13. TRANSPORT INDEX
 N/A

14. PHYSICAL AND CHEMICAL FORM
 Solid Metal Oxides

15. RADIOACTIVE MATERIALS
 Pu-241 (1-12P-LLD)
 Pu-241 (1-12P-LLD)
 Pu-241 (1-12P-LLD)
 Pu-241 (1-12P-LLD)

16. TOTAL PACKAGE ACTIVITY IN SILVERTS
 1,19E+01 MBq (0.21E+01 mCi)

17. HAZARDOUS CLASS
 LSA II

18. TOTAL WEIGHT OR VOLUME (See appropriate units)
 530.7 Kg
 1170.0 Lbs

19. IDENTIFICATION NUMBER OF PACKAGE
 0198

20. SIGNATURE - Authorized carrier acknowledging waste receipt
 KAREN KERRY
 DATE: 7-11-00

21. SIGNATURE - Authorized consignor acknowledging waste receipt
 Robert E. Bandy
 DATE: 7/11/00

22. SHIPPING DATE
 07/11/2000

23. TELEPHONE NUMBER (Include Area Code)
 (615) 461-0272

24. EPA ID NUMBER
 N/A

25. COLLECTOR
 02000-8

26. PROCESSOR
 X (Repeat) NP

27. FORM 540 AND 541A, 541B, 541C, 541D, 541E, 541F, 541G, 541H, 541I, 541J, 541K, 541L, 541M, 541N, 541O, 541P, 541Q, 541R, 541S, 541T, 541U, 541V, 541W, 541X, 541Y, 541Z, 541AA, 541AB, 541AC, 541AD, 541AE, 541AF, 541AG, 541AH, 541AI, 541AJ, 541AK, 541AL, 541AM, 541AN, 541AO, 541AP, 541AQ, 541AR, 541AS, 541AT, 541AU, 541AV, 541AW, 541AX, 541AY, 541AZ, 541BA, 541BB, 541BC, 541BD, 541BE, 541BF, 541BG, 541BH, 541BI, 541BJ, 541BK, 541BL, 541BM, 541BN, 541BO, 541BP, 541BQ, 541BR, 541BS, 541BT, 541BU, 541BV, 541BW, 541BX, 541BY, 541BZ, 541CA, 541CB, 541CC, 541CD, 541CE, 541CF, 541CG, 541CH, 541CI, 541CJ, 541CK, 541CL, 541CM, 541CN, 541CO, 541CP, 541CQ, 541CR, 541CS, 541CT, 541CU, 541CV, 541CW, 541CX, 541CY, 541CZ, 541DA, 541DB, 541DC, 541DD, 541DE, 541DF, 541DG, 541DH, 541DI, 541DJ, 541DK, 541DL, 541DM, 541DN, 541DO, 541DP, 541DQ, 541DR, 541DS, 541DT, 541DU, 541DV, 541DW, 541DX, 541DY, 541DZ, 541EA, 541EB, 541EC, 541ED, 541EE, 541EF, 541EG, 541EH, 541EI, 541EJ, 541EK, 541EL, 541EM, 541EN, 541EO, 541EP, 541EQ, 541ER, 541ES, 541ET, 541EU, 541EV, 541EW, 541EX, 541EY, 541EZ, 541FA, 541FB, 541FC, 541FD, 541FE, 541FF, 541FG, 541FH, 541FI, 541FJ, 541FK, 541FL, 541FM, 541FN, 541FO, 541FP, 541FQ, 541FR, 541FS, 541FT, 541FU, 541FV, 541FW, 541FX, 541FY, 541FZ, 541GA, 541GB, 541GC, 541GD, 541GE, 541GF, 541GG, 541GH, 541GI, 541GJ, 541GK, 541GL, 541GM, 541GN, 541GO, 541GP, 541GQ, 541GR, 541GS, 541GT, 541GU, 541GV, 541GW, 541GX, 541GY, 541GZ, 541HA, 541HB, 541HC, 541HD, 541HE, 541HF, 541HG, 541HH, 541HI, 541HJ, 541HK, 541HL, 541HM, 541HN, 541HO, 541HP, 541HQ, 541HR, 541HS, 541HT, 541HU, 541HV, 541HW, 541HX, 541HY, 541HZ, 541IA, 541IB, 541IC, 541ID, 541IE, 541IF, 541IG, 541IH, 541II, 541IJ, 541IK, 541IL, 541IM, 541IN, 541IO, 541IP, 541IQ, 541IR, 541IS, 541IT, 541IU, 541IV, 541IW, 541IX, 541IY, 541IZ, 541JA, 541JB, 541JC, 541JD, 541JE, 541JF, 541JG, 541JH, 541JI, 541JJ, 541JK, 541JL, 541JM, 541JN, 541JO, 541JP, 541JQ, 541JR, 541JS, 541JT, 541JU, 541JV, 541JW, 541JX, 541JY, 541JZ, 541KA, 541KB, 541KC, 541KD, 541KE, 541KF, 541KG, 541KH, 541KI, 541KJ, 541KK, 541KL, 541KM, 541KN, 541KO, 541KP, 541KQ, 541KR, 541KS, 541KT, 541KU, 541KV, 541KW, 541KX, 541KY, 541KZ, 541LA, 541LB, 541LC, 541LD, 541LE, 541LF, 541LG, 541LH, 541LI, 541LJ, 541LK, 541LM, 541LN, 541LO, 541LP, 541LQ, 541LR, 541LS, 541LT, 541LU, 541LV, 541LW, 541LX, 541LY, 541LZ, 541MA, 541MB, 541MC, 541MD, 541ME, 541MF, 541MG, 541MH, 541MI, 541MJ, 541MK, 541ML, 541MN, 541MO, 541MP, 541MQ, 541MR, 541MS, 541MT, 541MU, 541MV, 541MW, 541MX, 541MY, 541MZ, 541NA, 541NB, 541NC, 541ND, 541NE, 541NF, 541NG, 541NH, 541NI, 541NJ, 541NK, 541NL, 541NM, 541NO, 541NP, 541NQ, 541NR, 541NS, 541NT, 541NU, 541NV, 541NW, 541NX, 541NY, 541NZ, 541OA, 541OB, 541OC, 541OD, 541OE, 541OF, 541OG, 541OH, 541OI, 541OJ, 541OK, 541OL, 541OM, 541ON, 541OO, 541OP, 541OQ, 541OR, 541OS, 541OT, 541OU, 541OV, 541OW, 541OX, 541OY, 541OZ, 541PA, 541PB, 541PC, 541PD, 541PE, 541PF, 541PG, 541PH, 541PI, 541PJ, 541PK, 541PL, 541PM, 541PN, 541PO, 541PP, 541PQ, 541PR, 541PS, 541PT, 541PU, 541PV, 541PW, 541PX, 541PY, 541PZ, 541QA, 541QB, 541QC, 541QD, 541QE, 541QF, 541QG, 541QH, 541QI, 541QJ, 541QK, 541QL, 541QM, 541QN, 541QO, 541QP, 541QQ, 541QR, 541QS, 541QT, 541QU, 541QV, 541QW, 541QX, 541QY, 541QZ, 541RA, 541RB, 541RC, 541RD, 541RE, 541RF, 541RG, 541RH, 541RI, 541RJ, 541RK, 541RL, 541RM, 541RN, 541RO, 541RP, 541RQ, 541RS, 541RT, 541RU, 541RV, 541RW, 541RX, 541RY, 541RZ, 541SA, 541SB, 541SC, 541SD, 541SE, 541SF, 541SG, 541SH, 541SI, 541SJ, 541SK, 541SL, 541SM, 541SN, 541SO, 541SP, 541SQ, 541SR, 541SS, 541ST, 541SU, 541SV, 541SW, 541SX, 541SY, 541SZ, 541TA, 541TB, 541TC, 541TD, 541TE, 541TF, 541TG, 541TH, 541TI, 541TJ, 541TK, 541TL, 541TM, 541TN, 541TO, 541TP, 541TQ, 541TR, 541TS, 541TT, 541TU, 541TV, 541TW, 541TX, 541TY, 541TZ, 541UA, 541UB, 541UC, 541UD, 541UE, 541UF, 541UG, 541UH, 541UI, 541UJ, 541UK, 541UL, 541UM, 541UN, 541UO, 541UP, 541UQ, 541UR, 541US, 541UT, 541UU, 541UV, 541UW, 541UX, 541UY, 541UZ, 541VA, 541VB, 541VC, 541VD, 541VE, 541VF, 541VG, 541VH, 541VI, 541VJ, 541VK, 541VL, 541VM, 541VN, 541VO, 541VP, 541VQ, 541VR, 541VS, 541VT, 541VU, 541VV, 541VW, 541VX, 541VY, 541VZ, 541WA, 541WB, 541WC, 541WD, 541WE, 541WF, 541WG, 541WH, 541WI, 541WJ, 541WK, 541WL, 541WM, 541WN, 541WO, 541WP, 541WQ, 541WR, 541WS, 541WT, 541WU, 541WV, 541WW, 541WX, 541WY, 541WZ, 541XA, 541XB, 541XC, 541XD, 541XE, 541XF, 541XG, 541XH, 541XI, 541XJ, 541XK, 541XL, 541XM, 541XN, 541XO, 541XP, 541XQ, 541XR, 541XS, 541XT, 541XU, 541XV, 541XW, 541XX, 541XY, 541XZ, 541YA, 541YB, 541YC, 541YD, 541YE, 541YF, 541YG, 541YH, 541YI, 541YJ, 541YK, 541YL, 541YM, 541YN, 541YO, 541YP, 541YQ, 541YR, 541YS, 541YT, 541YU, 541YV, 541YW, 541YX, 541YY, 541YZ, 541ZA, 541ZB, 541ZC, 541ZD, 541ZE, 541ZF, 541ZG, 541ZH, 541ZI, 541ZJ, 541ZK, 541ZL, 541ZM, 541ZN, 541ZO, 541ZP, 541ZQ, 541ZR, 541ZS, 541ZT, 541ZU, 541ZV, 541ZW, 541ZX, 541ZY, 541ZZ

28. CONTACT
 Karen Powers
 (950) 481-0272

29. DATE
 7/12/00

30. DATE
 7/11/00

31. DATE
 7/11/00

32. DATE
 7/11/00

33. DATE
 7/11/00

34. DATE
 7/11/00

35. DATE
 7/11/00

36. DATE
 7/11/00

37. DATE
 7/11/00

38. DATE
 7/11/00

39. DATE
 7/11/00

40. DATE
 7/11/00