

# NRC INSPECTION MANUAL

IIPB

---

Change Notice 00-016

---

DELETED:

	<u>Number</u>	<u>Date</u>
1.	IP 60853	02/01/96
2.	IP 83822	04/09/00

TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IP 60853	09/07/00
	IP 83822	09/07/00

TRAINING: No special training requirements have been identified for any documents issued with this change notice.

REMARKS: IP 60853 (On-Site Fabrication of Components and Construction of an ISFSI) has been revised to incorporate lessons learned from inspections conducted over the past three years, as well as format changes and the use of "plain English." No significant change in FTE or DIE has occurred.

IP 83822 (Radiation Protection) has been revised to make the procedure more performance based.

DISTRIBUTION: Standard

END