

DI	A	1	/1	D	BWR Vessel & Internals Project	
D١	٧V	1	/		BWR Vessel & Internals Project	2000-312

Date November 6, 2000

Document Control Desk
U. S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852

Attn: C.E. Carpenter

Subject:

Project 704 - "BWR Vessel and Internals Project, Guidelines for Selection and

Use of Materials for Repairs to BWR Internals (BWRVIP-84)," EPRI Report

1000248, October 2000

Enclosed are ten (10) copies of the document "BWR Vessel and Internals Project, Guidelines for Selection and Use of Materials for Repairs to BWR Internals (BWRVIP-84)," EPRI Report 1000248, October, 2000. This document is being submitted as a means of exchanging information with the NRC for the purpose of supporting generic regulatory improvements related to the repair of BWR internals.

Please note that the enclosed document contains proprietary information. A letter requesting the report be withheld from public disclosure and an affidavit describing the basis for withholding this information are provided as Attachment 1.

If you have any questions on this subject please call Bruce McLeod, BWRVIP Repair Committee Technical Chairman, at (205) 992-7446.

Sincerely,

Carl Terry

Niagara Mohawk Power Company

Chairman, BWR Vessel and Internals Project

Enclosure

D058