



**NOV 16 2000**

LRN-00-0441

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Gentlemen:

**STEAM GENERATOR TUBE PLUGGING REPORT  
TECHNICAL SPECIFICATION 4.4.6.5.A  
SALEM GENERATING STATION UNIT NO. 2  
FACILITY OPERATING LICENSE DPR-75  
DOCKET NO. 50-311**

PSEG Nuclear LLC hereby submits the steam generator tube plugging report for Salem Generating Station, Unit no. 2 as required by Technical Specification 4.4.6.5.a for Facility Operating License DPR-75. The Steam Generator Tube inspections were completed on November 2, 2000 during the Unit 2 11<sup>th</sup> refueling outage.

The following is a summary of the tubes plugged during 2R11 as a result of eddy current inspections:

Steam Generator #21 -	31 tubes
Steam Generator #22 -	33 tubes
Steam Generator #23 -	17 tubes
Steam Generator #24 -	37 tubes

Total Salem Unit No. 2 steam generator tube plugging is 6.43%

Should there be any questions regarding this submittal, please contact Brooke Knieriem, Licensing at (856) 339-1782.

A handwritten signature in black ink, appearing to read "D.F. Garchow".

D. F. Garchow  
Acting Vice President - Operations

A001

RBK

C Distribution