

November 28, 2000

Ms. Judith Ordan
Apartment D-1
150 North Bedford Road
Chappaqua, NY 10514

Dear Ms. Ordan:

I am responding to your letter of July 13, 2000, to Mrs. Hillary Clinton concerning an event at Consolidated Edison Company of New York's (ConEd) Indian Point Nuclear Generating Unit No. 2 (IP2). The event involved a steam generator tube failure in one of the plant's four steam generators.

As the cognizant authority for regulating commercial nuclear power plant operation, the U.S. Nuclear Regulatory Commission (NRC) sets minimum requirements that must be met to assure protection of public health and safety. The NRC shares your concern about events at IP2 and recognizes the importance of our continued attention to ConEd's corrective actions. The NRC staff has been involved with the review of steam generator tube integrity activities at IP2 associated with the February 2000 event. This involvement has included direct observation of steam generator inspections performed by ConEd and detailed review of inspection data and results as they relate to steam generator tube integrity.

On August 8, 2000, ConEd informed the NRC that a decision was made to replace the existing steam generators. ConEd completed replacement of the steam generators in November 2000.

I thank you for your interest in this matter and I trust that this letter addresses your concerns.

Sincerely,

/RA by Brian W. Sheron for/

Samuel J. Collins, Director
Office of Nuclear Reactor Regulation

Ms. Judith Ordan
 Apartment D-1
 150 North Bedford Road
 Chappaqua, NY 10514

November 28, 2000

Dear Ms. Ordan:

I am responding to your letter of July 13, 2000, to Mrs. Hillary Clinton concerning an event at Consolidated Edison Company of New York's (ConEd) Indian Point Nuclear Generating Unit No. 2 (IP2). The event involved a steam generator tube failure in one of the plant's four steam generators.

As the cognizant authority for regulating commercial nuclear power plant operation, the U.S. Nuclear Regulatory Commission (NRC) sets minimum requirements that must be met to assure protection of public health and safety. The NRC shares your concern about events at IP2 and recognizes the importance of our continued attention to ConEd's corrective actions. The NRC staff has been involved with the review of steam generator tube integrity activities at IP2 associated with the February 2000 event. This involvement has included direct observation of steam generator inspections performed by ConEd and detailed review of inspection data and results as they relate to steam generator tube integrity.

On August 8, 2000, ConEd informed the NRC that a decision was made to replace the existing steam generators. ConEd completed replacement of the steam generators in November 2000.

I thank you for your interest in this matter and I trust that this letter addresses your concerns.

Sincerely,

/RA by Brian W. Sheron for/

Samuel J. Collins, Director
 Office of Nuclear Reactor Regulation

Pkg. ML003771885

*See previous concurrence.

Inc. ML003769784

DOCUMENT NAME: C:\g20000533.wpd Ltr. ML003771868

OFFICE	PDI-1\PM	PDI-1\LA	PDI-1\PM	PDI\SC	R-IDRP\PB2	PD-IPD
NAME	LBurkhart	SLittle*	PMilano*	MGamberoni*	PEselgroth via fax	EAdensam*
DATE	11/22/00	11/22/00	11/22/00	11/22/00	11/22/00	11/22/00
OFFICE	D\DD\DLPM	TECH-ED	ADPT	NRR:DD	NRR:D	
NAME	JZwolinski/SBlack*	11/24/00 N.L.A.	BSheron	BSheron for RZimmerman	BSheron for SCollins	
DATE	11/22/00		11/24/00	11/24/00	11/24/00	

Official Record Copy

Date: November 28, 2000

DISTRIBUTION:

PUBLIC

PDI-1 Reading

EDO G20000533

WTravers

FMiraglia

MKnapp

PNorry

JBlaha

SCollins/RZimmerman

BSheron

EAdensam

MGamberoni

OGC

OPA

OCA

NRR Mail Room (EDO G20000533)

MKing

MMcAllister

LBurkhart

PMilano

SLittle

J. Rogge, Region I