

November 28, 2000

Mr. R. P. Powers
Senior Vice President
Nuclear Generation Group
American Electric Power Company
500 Circle Drive
Buchanan, MI 49107-1395

SUBJECT: RESOLUTION OF CONTAINMENT STRUCTURAL ISSUES AT
DONALD C. COOK PLANT UNITS 1 AND 2

Dear Mr. Powers:

This letter acknowledges receipt of a letter from M. W. Rencheck, Vice President Nuclear Engineering, dated November 18, 2000, regarding the resolution of containment structural issues at D. C. Cook. We thank you for your timely response and acknowledge your corrective action plans to resolve the Unit 1 and 2 containment issues by the end of the next scheduled refueling outages. Also, as you indicated, should circumstances warrant that your corrective actions can not be completed prior to the end of the next refueling outages, such delays would be explicitly justified in your deficiency tracking system. We will continue to monitor your progress in resolving these issues through periodic public meetings.

Sincerely,

Geoffrey E. Grant, Director
Division of Reactor Projects

Docket Nos. 50-315; 50-316
License Nos. DPR-58; DPR-74

See Attached Distribution

DOCUMENT NAME: G:\cook\resolution ltr.wpd

To receive a copy of this document, indicate in the box: "C" = Copy without enclosure "E"= Copy with enclosure "N"= No copy

OFFICE	RIII	C	RIII	C	RIII		
NAME	Veigel/trn		Bajwa		Grant		
DATE	11/28/00		11/28/00		11/28/00		

OFFICIAL RECORD COPY

cc: A. C. Bakken III, Site Vice President
J. Pollock, Plant Manager
M. Rencheck, Vice President, Nuclear Engineering
R. Whale, Michigan Public Service Commission
Michigan Department of Environmental Quality
Emergency Management Division
MI Department of State Police
D. Lochbaum, Union of Concerned Scientists

ADAMS Distribution:

RRB1

DFT

JFS2 (Project Mgr.)

J. Caldwell, RIII

G. Grant, RIII

B. Clayton, RIII

SRI D. C. Cook

DRP

DRSIII

PLB1

JRK1

BAH3