

November 30, 2000 3F1100-10

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555-0001

Subject: Report Required by Environmental Protection Plan

Dear Sir:

The Crystal River Unit 3 (CR-3) Environmental Protection Plan (EPP), Appendix B of the CR-3 Operating License, establishes reporting requirements related to environmental conditions. Section 4.1, "Significant Environmental Events," requires that reports to other Federal, State or local agencies shall be copied to the Nuclear Regulatory Commission (NRC).

The National Marine Fisheries Service (NMFS), NRC, and the Crystal River Energy Complex completed an Endangered Species Act Section 7 formal consultation process in 1999. The Biological Opinion issued by the NMFS include terms and conditions which require that a written report be submitted to NMFS for sea turtle mortality occurring at the Crystal River Energy Complex.

A report of a sea turtle mortality (see attached) has been made to the National Marine Fisheries Service.

If you have any questions regarding this submittal, please contact Mr. Sid Powell, Manager, Nuclear Licensing at (352) 563-4883.

Sincerely,

John J. Holden Vice President and Site Director

JJH/smg

Attachment

xc: Regional Administrator, Region II Senior Resident Inspector NRR Project Manager

njool

## FLORIDA POWER CORPORATION CRYSTAL RIVER UNIT 3 DOCKET NUMBER 50-302/LICENSE NUMBER DPR-72

ATTACHMENT

SEA TURTLE REPORT



November 30, 2000 NL00-0128

US National Marine Fisheries Service South East Regional Office Attn: Assistant Regional Administrator Protected Resource Division 9721 Executive Center Dr., Suite 102 St. Petersburg, FL 33707

Subject: Sea Turtle Report

Dear Sir:

The National Marine Fisheries Service (NMFS), Nuclear Regulatory Commission, and the Crystal River Energy Complex completed an Endangered Species Act Section 7 formal consultation process in 1999. The Biological Opinion issued by the NMFS include terms and conditions which require that a written report be submitted for sea turtle injury or mortality occurring at the Crystal River Energy Complex.

On November 6, 2000, a sea turtle carcass was discovered on a subsurface area of a Crystal River Unit 3 intake bar rack. As the bar rack was being lifted up onto the intake structure deck for cleaning, the carcass floated free and partial skeletal remains were recovered. The circumstances associated with the death of the turtle were discussed with the Florida Fish and Wildlife Conservation Commission (FWC). In the absence of any obvious injury or disease, Florida Power Corporation has concluded that the mortality was causally-related.

If you have any questions regarding this submittal, please contact Mr. Steve Garry, Supervisor, Environmental and Radiological Compliance at (352) 563-4777.

Sincerely,

Atto lin

John J. Holden Vice President and Site Director

JJH/SMG

xc: Records Management File