

Millstone Unit 2 Regulatory Conference

AGENDA

- Introduction - J. Linville
- Process Overview - R. Urban
- Issues and Concerns - J. Linville
- Licensee Presentation
- Closing Remarks - H. Miller

White Finding and Apparent Violation

- August 23, surveillance test reveals turbine-driven AFW pump controls sluggish
- Problem documented in a Condition Report, but initial evaluation was inappropriate
- September 20, surveillance test reveals that turbine-driven AFW pump controls were failed
- Failure mechanism would have prevented operator recovery of failed pump

NRC Concerns

- Recent performance trends
 - Acceptance of untimely or incomplete corrective actions
 - Inadequate human performance related to post maintenance restoration & testing
- Instances of -
 - Inadequate engineering evaluation and resolution of identified problems
 - Aging and degraded equipment