



DEC 14 2000

LRN-00-0477

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

**MONTHLY OPERATING REPORT
SALEM GENERATING STATION UNIT 1
DOCKET NO. 50-272**

In compliance with Section 6.9, Reporting Requirements for the Salem Unit 1 Technical Specifications, the operating statistics for **November 2000** are being forwarded. Also being forwarded, pursuant to the requirements of 10CFR50.59(b), is a summary of changes, tests, and experiments that were implemented in **November 2000**.

Sincerely,

A handwritten signature in black ink, appearing to read "D. F. Garchow".

D. F. Garchow
Vice President – Operations

RBK
Attachments

C Distribution

JE24

INDEX

<u>SECTION</u>	<u>NUMBER OF PAGES</u>
Operating Data Report	1
Monthly Operating Summary	1
Summary of Changes, Tests, and Experiments	2

DOCKET NO.: 50-272
 UNIT: Salem 1
 DATE: 12/8/00
 COMPLETED BY: R. Knieriem
 TELEPHONE: (856) 339-1782

Reporting Period November 2000

OPERATING DATA REPORT

Design Electrical Rating (MWe-Net)
Maximum Dependable Capacity (MWe-Net)

No. of hours reactor was critical
No. of hours generator was on line (service hours)
Unit reserve shutdown hours
Net Electrical Energy (MWH)

1115		
1106		
Month	Year-to-date	Cumulative
720	7755	126299
720	7641	121893
0	0	0
788351	8208373	122829708

UNIT SHUTDOWNS

NO.	DATE	TYPE F=FORCED S=SCHEDULED	DURATION (HOURS)	REASON (1)	METHOD OF SHUTTING DOWN THE REACTOR (2)	CORRECTIVE ACTION/ COMMENT

(1) Reason

- A - Equipment Failure (Explain)
- B - Maintenance or Test
- C - Refueling
- D - Regulatory Restriction
- E - Operator Training/License Examination
- F - Administrative
- G - Operational Error (Explain)
- H - Other

(2) Method

- 1 - Manual
- 2 - Manual Trip/Scram
- 3 - Automatic Trip/Scram
- 4 - Continuation
- 5 - Other (Explain)

DOCKET NO.: 50-272
UNIT: Salem 1
DATE: 12/8/00
COMPLETED BY: R. Knieriem
TELEPHONE: (856) 339-1782

Summary Of Monthly Operating Experience

- Salem Unit 1 operated at full power throughout the month of November 2000.

DOCKET NO.: 50-272
UNIT: Salem 1
DATE: 12/8/00
COMPLETED BY: R. Knieriem
TELEPHONE: (856) 339-1782

SUMMARY OF CHANGES, TESTS, AND EXPERIMENTS
FOR THE SALEM GENERATING STATION – UNIT 1

MONTH November 2000

The following items completed during **November 2000** have been evaluated to determine:

1. If the probability of occurrence or the consequences of an accident or malfunction of equipment important to safety previously evaluated in the safety analysis report may be increased; or
2. If a possibility for an accident or malfunction of a different type than any evaluated previously in the safety analysis report may be created; or
3. If the margin of safety as defined in the basis for any technical specification is reduced.

The 10CFR50.59 Safety Evaluations showed that these items did not create a new safety hazard to the plant nor did they affect the safe shutdown of the reactor. These items did not change the plant effluent releases and did not alter the existing environmental impact. The 10CFR50.59 Safety Evaluations determined that no unreviewed safety or environmental questions are involved.

Design Changes Summary of Safety Evaluations

There were no reportable changes in this category implemented during November 2000.

Temporary Modifications Summary of Safety Evaluations

There were no reportable changes in this category implemented during November 2000.

Procedures Summary of Safety Evaluations

There were no reportable changes in this category implemented during November 2000.

SUMMARY OF CHANGES, TESTS, AND EXPERIMENTS
FOR THE SALEM GENERATING STATION – UNIT 1 – Cont.

UFSAR Change Notices Summary of Safety Evaluations

There were no reportable changes in this category implemented during November 2000.

Other - Summary of Safety Evaluations

There were no reportable changes in this category implemented during November 2000.