

- 3.10.2.8 Alarms are provided to indicate non-conformance with the flux difference requirements of 3.10.2.5.1 and the flux difference-time requirements of 3.10.2.6.1. If the alarms are temporarily out of service, conformance with the applicable limit shall be demonstrated by logging the flux difference at hourly intervals for the first 24 hours and half-hourly thereafter.
- 3.10.2.9 If the core is operating above 75% power with one excore nuclear channel out of service, then core quadrant power balance shall be determined once a day using movable incore detectors (at least two thimbles per quadrant).
- 3.10.3 Quadrant Power Tilt Limits
- 3.10.3.1 In the power operation condition, with thermal power greater than 50 percent rated thermal power, whenever the indicated quadrant power tilt ratio exceeds 1.02, except for physics tests, within two hours the tilt condition shall be eliminated or the following actions shall be taken:
- a. Restrict core power level and reset the power range high flux setpoint three percent of rated value for every percent of indicated power tilt ratio exceeding 1.0,
- and**
- b. If the tilt condition is not eliminated after 24 hours, the power range nuclear instrumentation setpoint shall be reset to 55% of allowed power. Subsequent reactor operation is permitted up to 50% for the purpose of measurement, testing and corrective action.
- 3.10.3.2 Except for physics tests, if the indicated quadrant power tilt ratio exceeds 1.09 and there is simultaneous indication of a misaligned control rod, restrict core power level 3% of rated value for every percent of indicated power tilt ratio exceeding 1.0 and realign the rod within two hours. If the rod is not realigned within two hours or if there is no simultaneous indication of a misaligned rod, the reactor shall be brought to the hot shutdown condition within 4 hours. If the reactor is shut down, subsequent testing up to 50% of rated power shall be permitted to determine the cause of the tilt.