

Dave Morey
Vice President
Farley Project

Southern Nuclear
Operating Company
P.O. Box 1295
Birmingham, Alabama 35201
Tel 205.992.5131

March 13, 2001

Docket Nos.: 50-348
50-364



Energy to Serve Your WorldSM

NEL-01-0061

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant
Monthly Operating Report

Ladies and Gentlemen:

Enclosed are the February 2001 Monthly Operating Reports for Joseph M. Farley Nuclear Plant Units 1 and 2, as required by Section 5.6.4 of the Technical Specifications.

If you have any questions, please advise.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Dave Morey".

Dave Morey

RWC:mor

Enclosures:

1. February Monthly Operating Report for Plant Farley Unit 1
2. February Monthly Operating Report for Plant Farley Unit 2

IE24

Page 2

U. S. Nuclear Regulatory Commission

cc: Southern Nuclear Operating Company
Mr. L. M. Stinson, General Manager

U. S. Nuclear Regulatory Commission, Washington, D. C.
Mr. F. Rinaldi, Licensing Project Manager – Farley

U. S. Nuclear Regulatory Commission, Region II
Mr. L. A. Reyes, Regional Administrator
Mr. T. P. Johnson, Senior Resident Inspector – Farley

OPERATING DATA REPORT

DOCKET NO.: 50-348
UNIT NAME: J. M. Farley - Unit 1
DATE: March 5, 2001
COMPLETED BY: W. L. Marlar
TELEPHONE: (334) 814-4554

OPERATING STATUS

1. Reporting Period: FEBRUARY 2001
 2. Design Electrical Rating (Net MWe): 854
 3. Maximum Dependable Capacity (Net MWe): 833

	<u>This Month</u>	<u>Year to Date</u>	<u>Cumulative</u>
4. Number Of Hours Reactor Was Critical:	672.0	1,416.0	165,853.7
5. Hours Generator On-line:	672.0	1,416.0	163,647.2
6. Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7. Net Electrical Energy Generated (MWH):	558,039.0	1,193,219.0	129,153,636.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		At 1233 on 010213 PORV 444 lifted for a brief period of time estimated to be between five and ten seconds and then closed without any operator action. This occurred as maintenance personnel were preparing to perform maintenance on the Reactor Protection System instrumentation. No safety valves lifted. This PORV did not operate to relieve a high pressure condition. The minimum pressurizer pressure was 2155 psig. The cause was attributed to an intermittent loss of power to a Reactor Protection system instrumentation circuit card.

UNIT SHUTDOWNS

DOCKET NO.: 50-348

UNIT NAME: J. M. Farley - Unit 1

DATE: March 5, 2001

COMPLETED BY: W. L. Marlar

TELEPHONE: (334) 814-4554

REPORTING PERIOD: FEBRUARY 2001

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
						There were no unit shutdowns during the month.

(1) REASON:

- A - Equipment Failure (Explain)
- B - Maintenance or Test
- C - Refueling
- D - Regulatory Restriction
- E - Operator Training/License Examination
- F - Administrative
- G - Operational Error (Explain)
- H - Other (Explain)

(2) METHOD:

- 1 - Manual
- 2 - Manual Trip/Scram
- 3 - Automatic Trip/Scram
- 4 - Continuation
- 5 - Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

At 2200 on 010215 the unit was ramped down to approximately 63% power to repair a Steam Generator Feed Pump lube oil temperature control problem. The unit was returned to 100% power at 2151 on 010217.

OPERATING DATA REPORT

DOCKET NO.: 50-364
UNIT NAME: J. M. Farley - Unit 2
DATE: March 5, 2001
COMPLETED BY: W. L. Marlar
TELEPHONE: (334) 814-4554

OPERATING STATUS

1. Reporting Period: FEBRUARY 2001
 2. Design Electrical Rating (Net MWe): 855
 3. Maximum Dependable Capacity (Net MWe): 842

	<u>This Month</u>	<u>Year to Date</u>	<u>Cumulative</u>
4. Number Of Hours Reactor Was Critical:	552.8	1,296.8	149,806.3
5. Hours Generator On-line:	552.1	1,296.1	147,920.1
6. Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7. Net Electrical Energy Generated (MWH):	466,477.0	1,103,598.0	117,918,684.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.

UNIT SHUTDOWNS

DOCKET NO.: 50-364

UNIT NAME: J. M. Farley - Unit 2

DATE: March 5, 2001

COMPLETED BY: W. L. Marlar

TELEPHONE: (334) 814-4554

REPORTING PERIOD: **FEBRUARY 2001**

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
1	010224	S	119.9	C	1	At 0004 on 010224 the unit was taken off line for the fourteenth refueling outage.

(1) REASON:

- A - Equipment Failure (Explain)
- B - Maintenance or Test
- C - Refueling
- D - Regulatory Restriction
- E - Operator Training/License Examination
- F - Administrative
- G - Operational Error (Explain)
- H - Other (Explain)

(2) METHOD:

- 1 - Manual
- 2 - Manual Trip/Scram
- 3 - Automatic Trip/Scram
- 4 - Continuation
- 5 - Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

At 0735 on 010223 Unit 2 started derating from 100% power due to power coastdown prior to a normal refueling outage. At 1700 on 010223 the unit was ramped down and taken off line at 0004 on 010224. The unit entered Mode 5 at 1235 on 010224.