

UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

I-H

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

10/2/63

1. LICENSEE National Research Corporation 70 Memorial Drive Cambridge, Massachusetts	2. REGIONAL OFFICE U. S. Atomic Energy Commission Region I, Division of Compliance 376 Hudson Street New York, New York 10014
3. LICENSE NUMBER(S) 20-1465-6	4. DATE OF INSPECTION September 27, 1963 (Reinspection)

5. INSPECTION FINDINGS

- A. No Item of noncompliance was found.
- B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 31.302
- C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 31.302
- D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)
- E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)
- F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)
- G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f) (4)
- H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)
- I. Form AEC-3 was not properly posted. 10 CFR 20.206(c)
- J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 31.203(b)
- K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 31.303(d)
- L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.41, 40.61 or 70.51
- M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 31.105(c).
- N. Records of inventories were not maintained. 10 CFR 31.106
- O. Utilization logs were not maintained. 10 CFR 31.107

Mailed to licensee: 10/2/63

Fred N. Brandkamp
(AEC Compliance Inspector)

6. LICENSEE'S ACKNOWLEDGMENT

The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.

ITEM # 21

A/21

(Date) (Licensee Representative - Title or Position)