

UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

I-H

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

10/2/63

| | |
|---|--|
| 1. LICENSEE National Research Corporation 70 Memorial Drive Cambridge, Massachusetts | 2. REGIONAL OFFICE U. S. Atomic Energy Commission Region I, Division of Compliance 376 Hudson Street New York, New York 10014 |
| 3. LICENSE NUMBER(S) 20-1465-6 | 4. DATE OF INSPECTION September 27, 1963 (Reinspection) |

5. INSPECTION FINDINGS

- A. No Item of noncompliance was found.
- B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 31.302
- C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 31.302
- D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)
- E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)
- F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)
- G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f) (4)
- H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)
- I. Form AEC-3 was not properly posted. 10 CFR 20.206(c)
- J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 31.203(b)
- K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 31.303(d)
- L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.41, 40.61 or 70.51
- M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 31.105(c).
- N. Records of inventories were not maintained. 10 CFR 31.106
- O. Utilization logs were not maintained. 10 CFR 31.107

Mailed to licensee: 10/2/63

Fred N. Brandkamp
(AEC Compliance Inspector)

6. LICENSEE'S ACKNOWLEDGMENT

The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.

ITEM # 21

A/21

(Date) _____ (Licensee Representative - Title or Position)