

T.S.6.9.1.6

May 10, 2001

Docket Nos. 50-352 50-353 License Nos. NPF-39 NPF-85

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Subject: Limerick Generating Station Monthly Operating Report For Units 1 and 2

Enclosed are the monthly operating reports for Limerick Units 1 and 2 for the month of April 2001 forwarded pursuant to Technical Specification 6.9.1.6.

Very truly yours,

ler.m

Robert C. Braun Plant Manager

ksm Jfw Enclosures

cc: H. J. Miller, Administrator, Region I, USNRC
A. L. Burritt, USNRC Senior Resident Inspector LGS
W. Levis, Vice President, LGS
J. M. Armstrong, Director-Site Engineering, LGS
S. T. Gamble, LGS Experience Assessment Branch, SSB2-4
P. R. Driehaus, Jr., LGS ISEG Branch, SMB-2-5

JE24

Docket No. 50-352 Attachment to Monthly Operating Report for April 2001

# Limerick Generating Station Unit 1 April 1 through April 30, 2001

# I. Narrative Summary of Operating Experiences

Unit 1 began the month of April 2001 at 100% of rated thermal power (RTP).

There were no reactor power changes on Unit 1 during the month.

Unit 1 ended the month of April 2001 at 100% RTP.

# II. Challenges to Main Steam Safety Relief Valves

There were no challenges to the Main Steam Safety Relief Valves during the month of April. There have been no challenges to the Main Steam Safety Relief Valves on Unit 1 year-to-date.

DOCKET NO. 50-352 DATE MAY 10, 2001 COMPLETED BY EXELON CORPORATION K. S. McLAUGHLIN REPORTS ENGINEER SITE ENGINEERING LIMERICK GENERATING STATION TELEPHONE (610) 718-3594 -

### **OPERATING STATUS**

1. UNIT NAME:	LIMERICK UNIT 1
	APRIL 2001
3. DESIGN ELECTRICAL RATING:	1143
4. MAXIMUM DEPENDABLE CAPACITY (GROSS MWE):	1183
5. MAXIMUM DEPENDABLE CAPACITY (NET MWE):	1143

	THIS MONTH	YR-TO-DATE	CUMULATIVE
6. NUMBER OF HOURS REACTOR WAS CRITICAL	719.0	2,861.6	115,674.2
7. REACTOR RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
8. HOURS GENERATOR ON-LINE	719.0	2,854.9	113,783.1
9. UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
10. NET ELECTRICAL ENERGY GENERATED (MWH)	839,154	3,348,989	115,697,889

#### UNIT SHUTDOWNS AND SIGNIFICANT LOAD REDUCTIONS

DOCKET NO. 50-352 UNIT LIMERICK UNIT 1 DATE MAY 10, 2001 COMPLETED BY EXELON CORPORATION K. S. McLAUGHLIN REPORTS ENGINEER SITE ENGINEERING LIMERICK GENERATING STATION TELEPHONE (610) 718-3594

REPORT MONTH APRIL 2001

			GENERATOR OFF LINE			
NO.	DATE	TYPE (1)	DURATION (HOURS)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR (3)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE

(1) Type F -- Forced S -- Scheduled (2)

### Reason

### A -- Equipment Failure

- B -- Maintenance or Test
- C Refueling
- z -- Refueling
- D -- Regulatory Restriction E -- Operational Training & License Examination
- F -- Administrative
- G -- Operational Error (Explain)
- H -- Other (Explain)

### (3)

- Method
- 1 -- Manual
- 2 Manual Scram
- 3 Automatic Scram
- 4 -- Other (Explain)

Docket No. 50-353 Attachment to Monthly Operating Report for April 2001

# Limerick Generating Station Unit 2 April 1 through April 30, 2001

# I. Narrative Summary of Operating Experiences

Unit 2 began the month of April 2001 at 83% of rated thermal power (RTP).

On April 1<sup>st</sup> at 0100 hours, reactor power was reduced to 76% RTP to return the 2C reactor feed pump to service. On April 1<sup>st</sup> at 0440 hours, reactor power was restored to 82% RTP.

On April 2<sup>nd</sup> at 0100 hours, reactor power was reduced to 76% RTP to remove 2B reactor feed pump and 2C condensate pump from service. On April 2<sup>nd</sup> at 0230 hours, reactor power was restored to 81% RTP.

On April 4<sup>th</sup> at 1000 hours, reactor power was reduced in preparation for the 2R06 refuel outage. On April 4<sup>th</sup> at 1450 hours with power reduced to 20% RTP, the reactor was manually scrammed to begin refueling outage 2R06.

On April 19<sup>th</sup> at 1620 hours, reactor criticality was achieved.

On April 20<sup>th</sup> at 2250 hours, the main generator was synchronized to the grid at 10% RTP. At 2356 hours the main generator was tripped due to high vibration on the main turbine. On April 21<sup>st</sup> at 0252 hours, the main generator was re-synchronized to the grid at 22% RTP. On April 23<sup>rd</sup> at 1200 hours reactor power was restored to 100% RTP.

On April 23<sup>rd</sup> at 2200 hours, reactor power was reduced from 97% to 70% RTP for a rod pattern adjustment. On April 24<sup>th</sup> at 0845 hours, reactor power was restored to 100% RTP.

On April 27<sup>th</sup> at 2200 hours, reactor power was reduced to 70% RTP for a rod pattern adjustment. On April 28<sup>th</sup> at 1353 hours, reactor power was restored to 100% RTP.

Unit 2 ended the month of April 2001 at 100% RTP.

### II. Challenges to Main Steam Safety Relief Valves

There were no challenges to the Main Steam Safety Relief Valves during the month of April. There has been one challenge to the Main Steam Safety Relief Valves on Unit 2 year-to-date.

DOCKET NO. 50-353 DATE MAY 10, 2001 COMPLETED BY EXELON CORPORATION K. S. McLAUGHLIN REPORTS ENGINEER SITE ENGINEERING LIMERICK GENERATING STATION TELEPHONE (610) 718-3594

#### OPERATING STATUS

1. UNIT NAME:	LIMERICK UNIT 2
2. REPORTING PERIOD:	APRIL 2001
3. DESIGN ELECTRICAL RATING:	1143
4. MAXIMUM DEPENDABLE CAPACITY (GROSS MWE):	1183
5. MAXIMUM DEPENDABLE CAPACITY (NET MWE):	1143

	THIS MONTH	YR-TO-DATE	CUMULATIVE
6. NUMBER OF HOURS REACTOR WAS CRITICAL	357.5	2,459.4	91,592.1
7. REACTOR RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
8. HOURS GENERATOR ON-LINE	323.2	2,398.2	89,930.0
9. UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
10. NET ELECTRICAL ENERGY GENERATED (MWH)	306,967	2,510,967	94,892,337

#### UNIT SHUTDOWNS AND SIGNIFICANT LOAD REDUCTIONS

DOCKET NO. 50-353 UNIT LIMERICK UNIT 2 DATE MAY 10, 2001 COMPLETED BY EXELON CORPORATION K. S. McLAUGHLIN REPORTS ENGINEER SITE ENGINEERING LIMERICK GENERATING STATION TELEPHONE (610) 718-3594 2.1

,

NO.	DATE	TYPE (1)	GENERATOR OFF LINE DURATION (HOURS)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR (3)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
384	04-Apr	S	392.8	C	2	REFUEL OUTAGE 2R06
385	20-Apr	S	2.9	C	4	START UP

REPORT MONTH APRIL 2001

(1)	(2)	(3)
Туре	Reason	Method
F Forced	A Equipment Failure	1 Manual
S Scheduled	B Maintenance or Test	2 - Manual Scram
	C Refueling	3 – Automatic Scram
	D – Regulatory Restriction	4 Other (Explain)
	E Operational Training & License Examination	
	F Administrative	
	G Operational Error (Explain)	
	H Other (Explain)	