



LRN-01-0151

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

**STEAM GENERATOR TUBE PLUGGING REPORT
TECHNICAL SPECIFICATION 4.4.5.5.a
SALEM GENERATING STATION UNIT NO. 1
FACILITY OPERATING LICENSE DPR-70
DOCKET NO. 50-272**

PSEG Nuclear LLC hereby submits the steam generator tube plugging report for Salem Generating Station, Unit No. 1 as required by Technical Specification 4.4.5.5.a for Facility Operating License DPR-70. The Steam Generator Tube inspections were completed on May 3, 2001 during the Unit 1 14th refueling outage.

The following is a summary of the tubes plugged during 1R14 as a result of eddy current inspections:

Steam Generator #11 -	6 tubes
Steam Generator #12 -	12 tubes
Steam Generator #13 -	11 tubes
Steam Generator #14 -	6 tubes

A total of 35 tubes were plugged during this outage.

Total Salem Unit No. 1 steam generator tube plugging is 0.258%

Should there be any questions regarding this submittal, please contact E. Villar at (856) 339-5456.

A handwritten signature in black ink, appearing to read "D.F. Garchow".

D. F. Garchow
Vice President - Operations

A001

C Mr. H. Miller, Administrator - Region I
 U. S. Nuclear Regulatory Commission
 475 Allendale Road
 King of Prussia, PA 19406

 Mr. R. Fretz, Licensing Project Manager - Salem
 U. S. Nuclear Regulatory Commission
 One White Flint North
 Mail Stop 4D3
 11555 Rockville Pike
 Rockville, MD 20852

 USNRC Resident Inspector Office (X24)

 Mr. K. Tosch, Manager IV
 Bureau of Nuclear Engineering
 P. O. Box 415
 Trenton, NJ 08625