

From: Michael Modes
To: Holian, Brian, Lanning, Wayne, Lew, David
Date: Fri, Apr 28, 2000 10:34 AM
Subject: IP2 SG Call 4/28

Because most of the work is done and IP2 is focusing on the final plugging list, the call was very brief.

Highlights:

The initially reported leak in S/G 23 was not from the generator but from the tubing used to attach the pressurizing equipment.

The data sheet was corrected for R30/C13. The volumetric indication is at 0.33" above TSH.

Thanks,
 M*
 Division of Reactor Safety
 Region I
 (610) 337- 5198
 FAX 5320

177-1507-1-03
 118

A/83