

From: Brian Holian
To: ArB, HJM1, JTW1, RVC, WDL
Date: Fri, Jul 14, 2000 4:07 PM
Subject: Fwd: Letter to Indian Point 2 -- going thru concurrence
Blough, Miller, Wiggins, Crenjak, Lanning
 attached ltr may not go out till Monday...

phoncon with IP2 (Baumstark) and Westinghouse on Insp Findings...(2 to 3:40 Fri)

ConEd and W position is that

- 1) what was the industry guidance in 97 that we did not follow?
- 2) although our logbooks don't show additional training etc. following the PWSCC indication on 2C67, we do have other data during that 97 inspection that shows we paused at "nebulous" data (e.g., crevice region)

NRC response... ConEd did not recognize significant conditions adverse to quality or implement effective corrective actions, as demonstrated by

- a) no recognizing the significance of, or adequately evaluating the flaw masking effects of, the high noise in the eddy current signal; and
- b) not adequately responding to a PWSCC indication in the U-bend of R2C67 (a new and significant degradation mechanism)

Brian

CC: DCL

ITEM # 164

A/114

(1)