

RECORD OF REJECTED K/As (COMPARABLE TO ES-401-10)

OF THE PERRY RETAKE EXAMINATION

ON JUNE 19, 2001

Memorandum

**To: Jim McHugh
Rick Strohl**

Mail Stop: TEC214

From: David Johnson

Date: 06/19/01

Phone: X5558

Mail Stop: TEC214

Subject: LC 99-01 Written Re-Exam Analysis Results

In accordance with NUREG-1021, ES-501, Section C.1, a Written Exam Performance Analysis was performed by Doug Pierson, Jim Kelly, and myself in order to evaluate the validity of questions missed by half or more of the applicants.

A spreadsheet was compiled to track each applicant's incorrect response to each exam question. If a question was missed by half or more of the applicants, the question was reviewed to determine if a question validity issue or a training deficiency issue existed.

Below is the corresponding Master question number and a determination if a question validity issue or training deficiency issue exists.

If a training deficiency exists, the deficiency will need to be further evaluated to determine the corrective action.

This memo does not identify the exact deficiency or the corrective action; the memo only identifies potential training deficiencies that require further evaluation by OTU and OPS.

Master Q#10 – Training deficiency Knowledge of various PEI-T23 Containment Temperature action steps involving specific Containment temperature values, including their bases, should be evaluated for more extensive training.

Master Q#22 – Training deficiency Knowledge of the bases for various PEI critical limits should be evaluated for more extensive training.

Master Q#33 – Training deficiency Knowledge of the purpose of the APRM ALARM LEVEL RECORD pushbutton for an IRM/APRM Recorder should be evaluated for more extensive training.

Master Q#34 – Training deficiency Knowledge of the response of the RHR SDC isolation logic during a loss of RPS bus event should be evaluated for more extensive training.

Master Q#43 – Training deficiency Knowledge of Feedwater controls which provide a RFPT speed demand signal should be evaluated for more extensive training.

Master Q#53 – Training deficiency Knowledge of Off-Gas air purge operation should be evaluated for more extensive training.

Master Q#64 – Training deficiency Knowledge of the specific individual charged with the command authority over all activities involving plant operations (even during an emergency) should be evaluated for more extensive training.

Master Q#106 – Training deficiency Knowledge of the preferred order of indications to be used to determine SP temperature, as discussed in the PEI Bases, should be evaluated for more extensive training.

Master Q#118 – Training deficiency Knowledge of the bases for the caution which requires RHR SDC flow to be maintained greater than 2000 gpm should be evaluated for more extensive training.

6/19/01

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

[illegible]

License Class 99-01 Written Re-Exam Analysis

Master #	131
SRO #	NA
RO #	100
Examinee	
Lausberg-SRO	NA
Ferrell- RO	
Bray- RO	
O'Connor- RO	
Correct Answer	A
Total Missed	