


# VERMONT YANKEE NUCLEAR POWER CORPORATION



P.O. Box 157, Governor Hunt Road  
Vernon, Vermont 05354-0157  
(802) 257-7711

July 25, 2001  
BVY 01-58

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

**Subject: Vermont Yankee Nuclear Power Station  
License No. DPR-28 (Docket No. 50-271)  
Reportable Occurrence No. LER 2001-03, Rev. 0**

As defined by 10CFR73.71, we are reporting the attached Reportable Occurrence as LER 2001-03, Rev. 0. This LER was reported on July 18, 2001. The cover letter contained an incorrect Transmittal Number (BVY 01-50). This cover letter provides the correct number. No changes have been made to LER 2001-03.

Sincerely,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Kevin H. Bronson  
Plant Manager

cc: USNRC Region I Administrator  
USNRC Resident Inspector - VYNPS  
USNRC Project Manager - VYNPS  
Vermont Department of Public Service

IE 22

LICENSEE EVENT REPORT (LER)

APPROVED BY OMB NO. 3150-0104 EXPIRES 06/30/2001

Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

FACILITY NAME (1)

VERMONT YANKEE NUCLEAR POWER STATION (VY)

DOCKET NUMBER (2)

05000271

PAGE (3)

Page 1 of 2

TITLE (4)

Denial of Unescorted Access Authorization Due to Withholding Information

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
06	20	01	2001	03	00	07	18	2001	SNPS	05000443

OPERATING MODE (9)	POWER LEVEL (10)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check one or more) (11)			
		20.2201(b)	20.2203(a)(2)(v)	50.73(a)(2)(i)	50.73(a)(2)(viii)
N	100	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Specify in Abstract below or in NRC Form 366A

LICENSEE CONTACT FOR THIS LER (12)

NAME

Kevin Bronson, Plant Manager

TELEPHONE NUMBER (include Area Code)

(802) 257-7711

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (12)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
N/A	N/A	N/A	N/A	N/A	N/A				
N/A	N/A	N/A	N/A	N/A	N/A				

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).

X NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

DESCRIPTION:

On 06/20/01, with the reactor at full power, Vermont Yankee (VY) denied unescorted access authorization to a contractor employee. The denial followed the disposition of a previously undisclosed criminal history received on 06/04/01. On 06/04/01, the contractor was flagged in the Personnel Access Data System (PADS) with an entry, which would alert other sites to contact VY prior to granting site access to this contractor. On 06/15/01, the contractor initiated a request for unescorted access authorization at the Seabrook Nuclear Power Station (SNPS). SNPS contacted VY in reference to the flagged PADS entry. VY requested an interview with the contractor. The contractor then stated that he withheld reporting the criminal record, mistakenly believing it to be out of the five-year scope for reporting. VY directed the contractor to produce documentation that would indicate the status of the record. While waiting to receive the documentation, VY consulted the psychological screening provider pertaining to the contractor's withholding of the criminal history. Upon re-screening of the MMPI test data and follow up interview, the psychological screening provider determined he would not have recommended unescorted access authorization, if the criminal history record had been known to him at the time access was granted. The contractor had temporary access authorization at VY from 04/20/01 to 05/13/01. There were no human performance, behavioral or work related performance issues identified with the contractor during the period of access.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET	YEAR	SEQUENTIA L NUMBER	REVISION NUMBER	PAGE (3)
VERMONT YANKEE NUCLEAR POWER STATION	05000271	2001	03	00	Page 2 of 2

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

CAUSE OF THE EVENT:

The contractor withheld information pertaining to his criminal history.

ANALYSIS:

VY Security personnel performed the screening process correctly and in accordance with approved procedures, which requires the reporting of all convictions. Criminal history records are not available when processing individuals for temporary unescorted access authorization. The contractor stated that he believed at the time of the initial screening, that criminal history beyond five years did not need to be reported. If this information had been known at the time access was granted, it would have precluded granting temporary unescorted access authorization at Vermont Yankee.

CORRECTIVE ACTIONS:

- 1) On 06/04/01, an entry was made to PADS pertaining to the contractor's incomplete criminal history, which would alert other sites to contact VY prior to authorizing access to the contractor.
- 2) On 06/20/01, the contractor's temporary unescorted access authorization at Vermont Yankee was revoked and PADS was updated to reflect this.

ADDITIONAL INFORMATION:

No similar security clearance events have occurred at Vermont Yankee.

Seabrook Nuclear Power Station initiated actions to deny unescorted access authorization to the contract worker.

Criminal history documentation was received from the individual verifying the conviction for which he failed to report.